

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5470H**AAD2110-***Not Authorized
C/Ly &*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

25 OCT 2021**SHC5470H**

VF1ABL15AUC280955

RENAULT

LATITUDE

22/10/2021

TOKIO

18/12/2014

PART	LIST
1 BUMPER COVER REAR	\$ <i>Bu</i> 561.70 ✓
1 BUMPER LOWER REAR	\$ <i>Bu</i> 411.90 ✓
1 BUMPER BRACKET CTR REAR	\$ <i>Bu</i> 98.10 X
1 BUMPER BRACKET SIDE RH REAR	\$ <i>D.I</i> 82.10 ✓
1 BUMPER REFLECTOR RH	\$ <i>CM</i> 16.60 ✓
1 BUMPER RETAINER RH REAR	\$ <i>D.I</i> 59.80 ✓
1 BUMPER BRACKET SIDE LH REAR	\$ <i>Bu</i> 80.80 X
1 BUMPER RETAINER LH REAR	\$ <i>Bu</i> 54.20 X
1 BUMPER BEAM REAR	\$ <i>Bu</i> 547.80 ✓
1 FENDER PANEL REAR RH	\$ <i>Bu</i> 1,933.20 ✓
1 WHEELARCH REAR RH	\$ <i>Bu</i> 275.40 X
1 OUTER PANEL REAR (End Panel)	\$ <i>Bu</i> 745.80 ✓
1 OUTER PANEL REAR (End Panel)TRIM	\$ <i>Bu</i> 404.56 ✓
1 BOOT REAR	\$ <i>Bu</i> 1,677.20 ✓
1 BOOT REFLECTOR LAMP LH	\$ <i>Bu</i> 277.70 X
1 BOOT BADGE 'RENAULT'	\$ <i>Bu</i> 82.40 ✓
1 BOOT BADGE	\$ <i>Bu</i> 95.80 ✓
1 BOOT HINGE LH	\$ <i>R</i> 254.20 X
1 BOOT HINGE RH	\$ <i>R</i> 254.20 X
1 BOOT STRUT LH	\$ <i>Bu</i> 145.10 X
1 BOOT STRUT RH	\$ <i>Bu</i> 145.10 X
1 BOOT LOCK	\$ <i>R</i> 246.60 X
1 BOOT LOCK CATCH	\$ <i>R</i> 41.70 X
1 BOOT FINISHER	\$ <i>Bu</i> 344.70 X
1 EXHAUST REAR	\$ <i>Bu</i> 5,263.60 <i>3500sm</i>
1 EXHAUST CAP REAR	\$ <i>Bu</i> 125.40 ✓
	\$ 8,836.66
	10% \$ 883.67

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5470H

AAD2110-

AAD2110

\$ 7,952.99**Special Nett**

1SET PARKING AID	\$	700.00	4005N
1SET REAR BUMPER CLIP	\$	66.00	✓
1 FENDER CLIP	\$	60.00	✓
1SET BUMPER BRACKET CTR CLIP	\$	33.00	X
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	20.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	10.00	X
1SET BUMPER RETAINER CLIP LH RR	\$	20.00	X
1SET BUMPER LOWER REAR CLIP	\$	66.00	✓
1 REAR BOOT STICKER 'Trans-cab'	\$	80.00	305N
1 REAR BOOT STICKER '6555-3333'	\$	80.00	305N
2 WINDSCREEN SEALANT	\$	150.00	405N
1 WINDSCREEN MOULDING	\$	200.00	X
1 WINDSCREEN INNER SPONGE SEAL	\$	130.00	305N
TOTAL	\$	1,625.00	
TOTAL PARTS	\$	9,577.99	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	8801
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	12001
To Rust-Proofing Of The Affected Areas.	\$	170.00	901
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	170.00	801

Trans-cab Auto Services Pte Ltd

AAD2110-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5470H

To drop rear exhaust box, renew the same, to repair
and realign centre exhaust pipe.

\$ *Renew* 170.00 X

To transfer of rear end panel fittings, attachment and
perform water seepage test.

\$ 170.00 *100%*

To transfer of rear windscreen fittings and conduct
water seepage test.

\$ 170.00 *120%*

To check steering geometry and computer wheel
alignment

\$ *220* 220.00 X

To Check Electrical Lighting Concerned.

\$ 170.00 *20%***TOTAL \$ 7,580.00****Over All Total \$ 25,110.99****(LUMP SUM)****Repair Days***20 DAYS*
*8 days***LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer**Signature:****Date:**