



PRIORITY SERVICES

Insurance Loss Adjusters and Motor Appraisers
Blk 779 #01-1545 Yishun Ave 2 Singapore 760779
Tel: 62934822 Fax: 62963283
E-mail: admin@priorityservices.sg

Date: 18 November 2020

Your Ref: CMTD2001287GPL

Our Ref: TP-0101/11/20

Motor Claims Department
M/s. Sompo Insurance Pte. Ltd.
50 Raffles Place #05-01/06
Singapore Land Tower
Singapore 048623

Attention: Mr. Gnoh Pau Loong

Dear Sir,

Inspection of 2012 Volkswagen Passat CC (A)
Registration No.: SKD 8647 E
Odometer Reading: 99611 km
Chassis No.: WVWZZZ3CZCE540247

We refer to your instructions to us to conduct a paper survey of the above vehicle. A pre-repair survey was conducted on 26-05-2020 and resurvey after repairs on 28-05-2020. No inspection of dismantled parts was necessary.

The following documents were received: -

- 1) Copy of survey report by M/s. Impact Analysis Consultant
- 2) 13 copies of photos depicting damages sustained by SKD 8647 E
- 3) Accident reports by drivers of SKD 8647 E and YP 8346 U

The vehicle sustained RHS rear damages during an accident on 14-03-2020.

Repair cost submitted was \$6,700.00 lump-sum.

We append below our findings: -

<u>Replacement of Parts</u>		<u>Revised Amount</u>	<u>Our Recommendation</u>
1pc.	Boot lid – repaired	\$ 3,250.00	\$ -
1pc.	Rear fender RH – repaired	2,850.00	-
1pc.	Rear windscreen glass moulding – not necessary	285.50	-
1pc.	Boot lid logo	112.00	112.00
1pc.	Boot lid emblem TBI	63.50	63.50
1pc.	Boot lid emblem PASSAT CC	115.80	115.80

		<u>\$ 6,676.80</u>	<u>\$ 291.30</u>
Less 10%		667.68	29.13
		<u>\$ 6,009.12</u>	<u>\$ 262.17</u>

Special Nett Items:-

1pc. Rear windscreen sealant – not necessary	\$ 50.00	\$ -
Total For Parts:-	<u>\$ 6,059.12</u>	<u>\$ 262.17</u>

Labour Charges:-

To dismantle, replace, cut, weld, knock out dents on boot lid and RH fender as mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$ 900.00	\$ 400.00
Putty and spray painting to adjacent panels. Job Allowance. Paint/material.	750.00	500.00
Apply rust proofing on the adjacent panels.	50.00	50.00
Remove and refix rear windscreen glass and inner trim to facilitate the replacement of rear fender. – not necessary	150.00	-
Wiring/bulb checking (inclusive of re-focus/readjust on angle of light intensity).	25.00	25.00
Total:-	<u>\$ 7,934.12</u>	<u>\$ 1,237.17</u>
Lump-sum repairs:	\$ 6,700.00	-
Part-By-Part repairs	"-	\$ 1,237.17

Estimated period of repairs: 3 working days

Pre-accident Market Value : About \$ 40,000.00
PARF/COE rebate : \$ 28,222.00

Vehicle within economical limit to repair.

We leave the decision of settlement to you.

Assuring you of our best services always

Yours faithfully

PRIORITY SERVICES

A handwritten signature in blue ink, appearing to read "Jimmy S. T. Lee", written over the printed name.

JIMMY S. T. LEE AMSOE, AMIRTE, MSAAA
Motor Appraiser

Surveyed by:

A handwritten signature in black ink, appearing to read "Jeffrey", written over the printed name.

JEFFREY ONG
Motor Appraiser