

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No: SDD7873H

Chassis No:

Engine No:

JTEKR33GH 10J004824

Report No

Date

25.10.2021

Denise.

Replacement of Damaged Parts

S/No.	QTY	Description	Condition / Remarks	LIST PRICE	LESS (25%)
1	1	Rear Bumper	Damaged Deformed	\$ 1,998.00	\$ 1,798.20
2	1	Rear Bumper Bracket LH	Necessary 2 NP	\$ 125.00	\$ 112.50
3	1	Rear Bumper Bracket RH	Necessary 2 NP	\$ 125.00	\$ 112.50
4	2	Rear Reverse sensor (Centre)	Faulty 1 piece damaged	\$ 300.00	\$ 270.00
5	1	Rear End Panel	Impacted Repair	\$ 755.00	\$ 679.50
6	1	Rear Bumper Diffuser	Damaged cut	\$ 456.00	\$ 410.40
7	1	Rear Right Reflector	Damaged Not Rec	\$ 221.00	\$ 198.90
8	1	Rear Right Boot	Impacted Not Rec	\$ 1,899.00	\$ 1,709.10
9	1	Rear Boot Weather Strips	Necessary Not Rec	\$ 212.00	\$ 190.80
10	1	Rear Boot Emblems 'Harrier'	Necessary Not Rec	\$ 145.00	\$ 130.50
11	1	Rear Boot Emblems 'Logo'	Necessary Not Rec	\$ 165.00	\$ 148.50
				\$ 6,401.00	\$ 5,120.80

12 1 Rear Bumper Sponge.

13 1 Rear End Panel Antenna Sensor

Total (Parts): \$ 6,401.00 -25% \$ 5,120.80

Labour Charges

26	To fix & dismantle and remove damaged Front Left Portions; affected damaged portion.	\$ 800.00	300
27	To apply anti rust coat and affected areas	\$ 180.00	30
28	To check wiring	\$ 180.00	30
29	Welding and cutting of affected panels, including chassis alignment	\$ -	
30	Spray painting for Front left Portions affected parts	\$ 1,000.00	400
31	Refocusing of the front headlamp	\$ -	
32	Diagnose ECU system and reset error code.	\$ 180.00	X
33	3D Wheel Alignment	\$ -	
34	To Apply Waterproofing sealer on End Panels	\$ 120.00	X

Total Labour: \$ 2,460.00

Total cost of repairs (Total cost of parts + Total Labour Cost) \$ 7,580.80

Less 20% \$ 6,064.64

AMM PTE LTD

Page 2 of 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 2098.75
r/s: 1.6K
03 Days.