



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2108581

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 13/12/2021
Reference CC6/CTI21010939/Uea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SNB 5672B
Insured Veh. GBK 9399J
Claim No. SNM21D206087/C02
Policy No. DMCVSNA00102552000
Accident Date 22/10/2021
Inspection Date 26/10/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21010939/Uea3q2 Date: 13/12/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBK 9399J	Veh. Inspected	SNB 5672B	
Policy No.	DMCVSNA00102552000	Coverage (\$)	0.00	
Claim No.	SNM21D206087/C02	Excess (\$)	0.00	
Assign From		Assign Date	26/10/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	MR2B23F3801171653	Colour	GREY	
Odometer	50382 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/50 R15	TURANZA	8 mm	
L/H Front Tyre	195/50 R15	TURANZA	8 mm	
R/H Rear Tyre	195/50 R15	TURANZA	8 mm	
L/H Rear Tyre	195/50 R15	TURANZA	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/10/2021	Inspection Date	26/10/2021	
Survey held at	SOON SAN MOTOR TRADING BLK 3006 UBI ROAD 1 #01-390 SINGAPORE 408716			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNB 5672B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	RIGHT FRONT DOOR	DENTED / BENT	849.30	849.30
2	RIGHT FRONT DOOR HINGES @\$81.20	LOWER BENT	162.40	81.20
1	RIGHT FRONT DOOR WEATHER STRIP	NECESSARY	157.70	157.70
1	RIGHT FRONT FENDER	BADLY DENTED	602.40	602.40
1	RIGHT FRONT FENDER INNER SHIELD	DISTORTED	275.50	275.50
10	RIGHT FRONT FENDER INNER SHIELD CLIPS @\$5.00	NECESSARY	50.00	50.00
1	FRONT SHOCK ABSORBER	NOT NECESSARY	463.80	-
1	RIGHT LOWER ARM	NOT NECESSARY	1,001.40	-
1	RIGHT KNUCKLE ARM	NOT NECESSARY	544.70	-
1	RIGHT KNUCKLE ARM BEARING	NOT NECESSARY	180.50	-
	LESS 20% DISCOUNT		-857.54	-
	LESS 25% DISCOUNT		-	-504.03
			3,430.16	1,512.07
1	SPORT RIM (O/S) (SN)	CUT	1,000.00	500.00
	LESS 20% DISCOUNT		-200.00	-
			800.00	500.00
	<u>LABOUR</u>			
	TO RUSTPROOF.		200.00	60.00
	TO COMPUTER WHEEL ALIGNMENT.		140.00	80.00
	TO DISMANTLE /RENEW DOOR .		150.00	60.00
	TO DISMANTLE /RENEW UNDERCARRIAGE FRONT.	NOT NECESSARY	200.00	-
	TO DISMANTLE /RENEW ACCIDENT PORTION.		1,200.00	400.00
	TO SPRAY PAINT.		1,000.00	600.00
			2,890.00	1,200.00
	GRAND TOTAL		7,120.16	3,212.07

Report Ref No. CC6/CTI21010939/Uea3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,500.00
---	--	--	----------

Report Ref No. CC6/CTI21010939/Uea3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SNB 5672B

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SNB 5672B

RE-INSPECTION

