

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SDW 2908A
Vehicle Model : MIT. LANCER EX
Accident Date : 24.10.2021
Original Reg Date : 23.02.2016

Date : 25.10.2021
Chassis : JMYSRCY1AGU003352
TP Ins. **AIG**

ESTIMATE

NETT

1	1 pc	Boot Lid		bt	852.00	794
2	1 pc	Boot Lid Badge		ne	52.00	
3	1 pc	Boot Lid Emblem LANCER		ne	56.00	
4	1 pc	Boot Lid Emblem CC		ne	40.00	
5	1 pc	Boot Lid Emblem MIVEC		ne	56.00	
6	1 pc	Boot Lid Lamp RH		RH ne	505.00	
7	2 set	Boot Lid Lamp Clips	LH X RH (30.00)	RH ne	60.00	
8	1 set	Boot Lid Insulator Clips		X RH	40.00	
9	1 pc	Boot Lid Stopper		ne	20.00	
10	1 pc	Boot Lid Inner Lock		X RH	136.00	
11	1 pc	Boot Lid Weatherstrip		twi	189.00	
12	2 pcs	Boot Lid Hinges	92.00	Ry	184.00	
13	2 pcs	Boot Lid Absorber	136.00	X RH	272.00	
14	1 pc	Rear Bumper		de	875.00	731
15	2 pcs	Rear Bumper Side Retainers	LH X RH (38.00)	RH de	76.00	
16	1 set	Rear Bumper Clips		3one	40.00	
17	1 pc	Rear Bumper Reflector RH		cm	84.00	
18	1 pc	Rear Bumper Top Beam		bt	210.00	
19	1 pc	Rear Bumper Reinforcement		bt	295.00	169
20	1 pc	End Panel		bt	592.00	420
21	1 pc	End Panel Top Trim		de	183.00	
22	1 set	End Panel Top Trim Clips		2one	30.00	
23	1 pc	Taillamp RH		one	795.00	
24	2 set	Taillamps Clips	LH X RH (25.00)	RH ne	50.00	
25	1 pc	Taillamps Panel		bt	129.00	
26	1 pc	Rear Fender RH		bu	695.00	
27	1 pc	Rear Fender Inner Trims		th	262.00	
28	1 set	Rear Fender Inner Trim Clips		ne	30.00	
29	1 pc	Rear Fender Inner Shield		th	38.00	
30	1 set	Rear Fender Inner Shield Clips		ne	20.00	

6,742.00
Less 10%
C/F 674.20
5621
5058.90

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C
#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : SDW 2908A

B/F

6,067.80

Special Nett

1	1 pc	Rear Bumper Top Chrome	bf ✓	480.00
2	1 set	Reverse Sensor	200mm ✓	250.00
3	1 set	Body Panel Joint Sealer	400mm ✓	120.00
4	1 pc	Rear Windscreen Sealant	400mm ✓	60.00
5	1 pc	Rear Windscreen Inner Seal	200mm ✓	40.00
6	1 pc	Boot Lid Top Spoiler Repair Kit	300mm ✓	60.00

380

710

Labour charge

Panel Beating	1200	1,800.00
Spray painting	1000	1,300.00
Check Wiring	30	40.00
Anti rust	30	120.00
Remove and install carpet and seat.	60	120.00
Remove and install reverse sensor	30	90.00
Remove and install windscreen	120	140.00

10,687.80

Less 20% 2,137.56

Lump sum 8,550.24

2470

Tan Jiah 97445741
WP' 27/10/2010 1130
L/S Resurvey After repair
08 days
Tan Jiah C/Hants 10/11/10

5058.90

710

2470

8238.90

4546600

08 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: