

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : China Taiping Insurance
(Singapore) Pte Ltd
3 Anson Road
#15-00 Springleaf Tower
Singapore 079909

Claim Details

Case Ref. No. : TP/102021/5041
Date : 25-10-2021
Accident Date : 22-10-2021

Vehicle Details

Make & Model : Volkswagen SHARAN 2.0 TSI
7N24MY
Chassis No : WVWZZZ7NZHV233834
Registration No : SLN1562Y

Third Party Vehicle Details

Registration No : SMZ2323P

S/N	Description	Qty	Amount (\$)
1	FRONT LH FENDER <i>Blue</i>	1.00	\$440.00
2	FRONT LH FENDER INNER SHIELD <i>✓ TN</i>	1.00	\$160.00
3	FRONT LH FENDER INNER SHIELD CLIPS @ \$5.00 <i>✓ Acc.</i>	10.00	\$50.00
4	LH SIDE MIRROR ASSY <i>✓ Cut</i>	1.00	\$670.00
5	LH SIDE MIRROR COVER	1.00	\$95.00
6	FRONT LH DOOR <i>Blue</i>	1.00	1456 \$1,750.00 <i>✓</i>
7	FRONT LH DOOR OUTER CHROME MOULDING <i>✓ De</i>	1.00	\$230.00
8	FRONT LH DOOR FRAME PILLAR STICKER <i>✓ Acc.</i>	1.00	\$155.00
9	FRONT LH DOOR OUTER HANDLE - LONG <i>✓ Cut</i>	1.00	\$340.00
10	FRONT LH DOOR OUTER HANDLE COVER - SMALL <i>✓ Cut</i>	1.00	\$25.00
11	FRONT LH DOOR LOWER PROTECTOR <i>✓ Cut</i>	1.00	\$270.00
12	FRONT LH DOOR TOP HINGE <i>x nn Cut</i>	1.00	\$90.00 <i>×</i>
13	FRONT LH DOOR LOWER HINGE <i>✓ BT</i>	1.00	\$90.00
14	FRONT LH DOOR INNER LOCK <i>✓ Im</i>	1.00	\$350.00
15	FRONT LH DOOR RUBBER <i>✓ Acc</i>	1.00	\$290.00
16	FRONT LH DOOR INNER TRIMBOARD <i>✓ CRA</i>	1.00	645 \$1,440.00 <i>1250</i>
17	FRONT LH DOOR POWER WINDOW MOTOR <i>✓ BR</i>	1.00	\$290.00
18	FRONT LH DOOR POWER WINDOW GEAR <i>✓ BT</i>	1.00	\$270.00
19	REAR LH DOOR <i>Blue</i>	1.00	\$2,100.00
20	REAR LH DOOR OUTER CHROME MOULDING <i>x nn</i>	1.00	\$235.00 <i>×</i>
21	REAR LH DOOR LOWER PROTECTOR <i>✓ Cut</i>	1.00	\$270.00
22	REAR LH DOOR OUTER HANDLE <i>x nn</i>	1.00	\$230.00 <i>×</i>
23	REAR LH DOOR VERTICAL RUBBER <i>✓ Cut</i>	1.00	\$360.00
24	REAR LH DOOR FRAME PILLAR STICKER - REAR <i>✓ Acc.</i>	1.00	\$125.00
25	LH CENTRE PILLAR <i>✓ Acc</i>	1.00	1100 \$1,550.00 <i>1390</i>
26	FRONT LH WHEEL SHOCK ABSORBER <i>✓ NN</i>	1.00	\$380.00 <i>×</i>
27	FRONT LH WHEEL KNUCKLE ARM <i>✓ BT</i>	1.00	\$440.00
28	FRONT LH WHEEL BEARING <i>✓ JM</i>	1.00	\$360.00
29	FRONT LH WHEEL LOWER ARM <i>✓ BT</i>	1.00	\$390.00
30	FRONT LH WHEEL SPORT RIM <i>✓ BT</i>	1.00	\$1,320.00 <i>600(SN)</i>

Vin's

Vin's Motor Pte Ltd
 160 Sin Ming Drive
 #03-03 Sin Ming Autocity
 Singapore 575722
 Tel : 6453 2121 Fax : 6459 9795
 GST Registration No. 199906067G

			\$14,765.00	
	Discount: -10%		(\$1,476.50)	
			\$13,288.50	
31	FRONT LH WHEEL TYRE <i>cut</i>	1.00	\$280.00	160 (cut)
32	TO CHECK WHEEL ALIGNMENT	1.00	\$150.00	60
33	TO REMOVE AND REFIX FRONT UNDERCARRIAGE	1.00	\$280.00	7 200
34	TO REPAIR DAMAGES	1.00	\$1,100.00	1000
35	TO SPRAY PAINTING	1.00	\$1,200.00	1000
	Subtotal w/o GST:		\$16,298.50	3020

8 Days.

P/P.

before paint photos.

Good to go

26/10/21.

~~10971~~ 12160

-10%: ~~9873.9~~ 10944

~~12093.9~~ 13964

LINK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Issued by Raymond Teo

This is a computer-generated document. No signature is required.