

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SGZ9114B Mazda 3

			Estimated Parts Price
No	Qty	Parts Description	
1	1	Front bumper assy	\$ 1,250.00 <i>de</i>
2	2	Front bumper retainer	\$ <i>RM</i> x 166.00 <i>RM de</i>
3	2	Front bumper bracket	\$ <i>RM</i> x 166.00 <i>RM de</i>
4	1	Front bumper lower grille	\$ 291.00 x
5	1	Front bumper reinforcement	\$ 378.00 <i>bt</i>
6	1	Front bumper tow cover	\$ 88.00 x
7	1	Front left fog lamp	\$ 240.00 x
8	1	Front left fog lamp garnish	\$ 68.00 x
9	1	Front grille assy	\$ 382.00 x
10	1	Front grille emblem	\$ 106.00 x
11	1	Front bonnet assy	\$ 1,431.00 <i>bt</i>
12	1	Front bonnet lock	\$ 179.00 x
13	1	Front bonnet lock catch	\$ 36.00 x
14	1	Front lock brace panel	\$ 123.00 x
15	1	Front left headlamp	\$ 1,498.00 <i>de</i>
16	1	Front left headlamp inner bracket	\$ 95.00 <i>de</i>
17	1	Front support panel assy	\$ 1,195.00 <i>de</i>
18	1	Front left suspension assy	\$ 832.00 x
19	1	Front left lower arm	\$ 420.00 x
20	1	Front left knuckle arm	\$ 425.00 x
21	1	Front left wheel hub with bearing	\$ 250.00 x
22	1	Front left fender lamp	\$ 68.00 x
23	1	Front left fender	\$ 897.00 <i>bt</i>
			\$ 10,584.00
less 20%			\$ 2,116.80
			\$ 8,467.20

Special Nett Items

1	12	Front bumper clips	\$ 60.00 <i>20</i>
2	6	Front bumper lower grille clips	\$ 40.00 x
3	6	Front grille clips	\$ 40.00 x
4	1	Front no plate	\$ 100.00 x
5	1	Front left wheel rim	\$ 680.00 x
6	1	Front left tyre	\$ 300.00 x
7	1	Front no plate with garnish	\$ 100.00 x
8	1	Front bumper lower spoiler	\$ 880.00 <i>de</i> / <i>400</i>
9	1	Front bumper lower spoiler sealant	\$ 100.00 <i>400</i>
10	10	Front bumper lower spoiler clips	\$ 50.00 <i>20</i>
			\$ 2,350.00

Total parts

\$ 10,817.20

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SGZ9114B Mazda 3

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts.	\$ 1,400.00 ⁸⁰⁰
2	To putty and spray painting front portion.	\$ 1,400.00 ⁸⁰⁰
3	To check wiring and focus front headlamp.	\$ 50.00 ³⁰
4	To remove and install front bonnet lock mechanism.	\$ 80.00
5	To apply anti rust proofing to front affected area.	\$ 140.00 ³⁰
6	To remove and install front left undercarriage parts.	\$ 350.00 ^X
7	To balance front left wheel.	\$ 50.00 ^X
8	To conduct wheel alignment.	\$ 120.00 ^X
9	Towing service.	\$ 100.00 ^X
Total labour :		\$ 3,690.00

Total parts : \$ 10,817.20

Total labour : \$ 3,690.00

Total repair cost : \$ 14,507.20

Tanph 97495749
 'up'
 4/5 Resurvey after repair
 Tanph 97495749
 06 days
 Repair limit 94000
 MV 9K
 Rebalance 4478

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed & is subject to final approval from Insurance

Acknowledged by Repairer

Signature:

Date: