

Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SGZ9114B Mazda 3

No	Qty	Parts Description	Estimated Parts Price
1	1	Front bumper assy	860 \$ 1,250.00 <i>de</i>
2	2	Front bumper retainer	<i>nn</i> \$ <i>RH</i> x 166.00 <i>RH de - 83</i>
3	2	Front bumper bracket	<i>nn</i> \$ <i>RH</i> x 166.00 <i>RH de - 83</i>
4	1	Front bumper lower grille	\$ 291.00 x <i>nn</i>
5	1	Front bumper reinforcement	\$ 378.00 <i>bt</i>
6	1	Front bumper tow cover	\$ 88.00 x <i>nn</i>
7	1	Front left fog lamp	\$ 240.00 x <i>nn</i>
8	1	Front left fog lamp garnish	\$ 68.00 x <i>nn</i>
9	1	Front grille assy	\$ 382.00 x <i>nn</i>
10	1	Front grille emblem	\$ 106.00 x <i>nn</i>
11	1	Front bonnet assy	920.60 \$ 1,431.00 <i>bt</i>
12	1	Front bonnet lock	\$ 179.00 x <i>nn</i>
13	1	Front bonnet lock catch	\$ 36.00 x <i>nn</i>
14	1	Front lock brace panel	\$ 123.00 x <i>nn</i>
15	1	Front left headlamp	813.60 \$ 1,498.00 <i>de</i>
16	1	Front left headlamp inner bracket	\$ 95.00 <i>de</i>
17	1	Front support panel assy	696 \$ 1,195.00 <i>de</i>
18	1	Front left suspension assy	\$ 832.00 x <i>nn</i>
19	1	Front left lower arm	\$ 420.00 x <i>nn</i>
20	1	Front left knuckle arm	\$ 425.00 x <i>nn</i>
21	1	Front left wheel hub with bearing	\$ 250.00 x <i>nn</i>
22	1	Front left fender lamp	\$ 68.00 x <i>nn</i>
23	1	Front left fender	398 \$ 897.00 <i>bt</i>
			\$ 10,584.00 <i>4327.20</i>
		less 20%	\$ 2,116.80
			\$ 8,467.20 <i>3461.76</i>

Special Nett Items

1	12	Front bumper clips	\$ 60.00 <i>20</i>
2	6	Front bumper lower grille clips	\$ 40.00 x
3	6	Front grille clips	\$ 40.00 x
4	1	Front no plate	\$ 100.00 x
5	1	Front left wheel rim	\$ 680.00 x
6	1	Front left tyre	\$ 300.00 x
7	1	Front no plate with garnish	\$ 100.00 x
8	1	Front bumper lower spoiler	\$ 880.00 <i>de</i> <i>4000</i>
9	1	Front bumper lower spoiler sealant	\$ 100.00 <i>4000</i>
10	10	Front bumper lower spoiler clips	\$ 50.00 <i>2000</i>
			\$ 2,350.00 <i>490</i>

Total parts

\$ 10,817.20

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SGZ9114B Mazda 3

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts.	\$ 1,400.00 800
2	To putty and spray painting front portion.	\$ 1,400.00 800
3	To check wiring and focus front headlamp.	\$ 50.00 30
4	To remove and install front bonnet lock mechanism.	\$ 80.00 xun
5	To apply anti rust proofing to front affected area.	\$ 140.00 30
6	To remove and install front left undercarriage parts.	\$ 350.00 x
7	To balance front left wheel.	\$ 50.00 x
8	To conduct wheel alignment.	\$ 120.00 x
9	Towing service.	\$ 100.00 x
Total labour :		\$ 3,690.00 1660

Total parts : \$ 10,817.20

Total labour : \$ 3,690.00

Total repair cost : \$ 14,507.20

Tanpha 97495749
 up

4/5 Resurvey after repair
 Tanpha 97495749
 06 days

Repair Unit 94000

MV 9K

Netrate 4478

3461.76
 490
 1660

5611.76

20% 4489.40

Repair Unit 94000

in COR 4/5 94000, 6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed & is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: