



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 2434H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRT FENDER RH	BENT	588.80	588.80
1	FRT WHEEL RIM RH	SCRATCHED	1,124.20	1,124.20
1	EMBLEM-BLUE DRIVE RH	NECESSARY	26.60	26.60
1	FRT DOOR RH	TO REPAIR SEE LABOUR	1,797.20	-
1	FRT DOOR PROTECTOR RH	NOT NECESSARY	186.20	-
	LESS 20% DISCOUNT		-744.60	-347.92
			2,978.40	1,391.68
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRT DOOR ADVERTISEMENT LOGO RH (SN)	NECESSARY	100.00	100.00
1	FRT FENDER ADVERTISEMENT LOGO RH (SN)	NECESSARY	100.00	100.00
1	FRT DOOR COMFORTDELGRO LOGO STICKER RH (SN)	NECESSARY	75.00	75.00
			275.00	275.00
<b><u>LABOUR</u></b>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRT DOOR RH.		1,050.00	525.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	TUFF KOTE.		60.00	40.00
	TRANSFER OF DOOR.	NOT NECESSARY	120.00	-
			1,830.00	1,065.00
<b>GRAND TOTAL</b>			<b>5,083.40</b>	<b>2,731.68</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>2,200.00</b>

Report Ref No. NS/INC21010960/R1tcn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.