

MODEL: Hyundai Ioniq

INSURANCE: NTUC (CLS)

VEHICLE NO.: SHC2919B

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Smart Key Antenna ? XAN	1		\$40.50
	Rear Bumper de	1		\$459.40
	Rear Bumper Reinforcement ? XAN	1		\$394.80
	Rear Bumper Reinforcement Bracket (LH/RH) ? XAN	2	\$138.10	\$276.20
	Rear Bumper Centre Moulding Assy de	1		\$451.25
	Rear Bumper Lower Centre Moulding Assy XAN	1		\$155.00
	Rear Bumper Cover Clips de	10	\$2.20	\$22.00
	Rear Bumper Fog Lamp X AN	1		\$201.50
	Rear Bumper Towing Cover XAN	1		\$98.80
SUB TOTAL				\$2,099.45
LESS 20%				\$419.89
DISCOUNTED TOTAL				\$1,679.56
	Rear Bumper Reverse Sensor ? XAN	1		\$180.00
	Rear No. Plate W/Trim Cover CA	1		\$55.00
SUB S/NETT				\$235.00
LESS 10%				\$23.50
SUB S/NETT TOTAL				\$211.50
	Rear Fender Adv. Sticker RH / LH de	2	\$100.00	\$200.00
	Rear Bumper Mat de	1		\$50.00
NETT TOTAL				\$250.00
SPARE PARTS TOTAL				\$2,141.06
Labour Charge				
	Panel Beating			\$400.00
	Spray Painting Charge			\$300.00
	Remove/Refix Reverse Sensor			\$120.00
TOTAL LABOUR				\$820.00
ESTIMATE TOTAL				\$2,961.06

968.65
20%
774.92

35
10%
31.50

250

350 } 640
250
40

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

774.92
31.50
250.00
640.00

1696.42
20%
1357.13
45 = \$1,350

Rasul
49 900 10068
3 days
43
25/10/21 @ 1550
Resy after repair