

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0667/2021/GW
DATE : 18-Aug-21
WIP :

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 18/8/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR LIM CHUAN AIK
ADDRESS : 81 PARIS RIS GROVE
#12-45
SINGAPORE 518210
TELEPHONE : HP +65 90128169
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900251964
VEHICLE NO : **SBX 8444 A**
MODEL CODE : A5 SB 2.0 TFSI S TRONIC
MODEL YEAR : 29/11/2019
ENGINE NO : CVK087541
CHASSIS NO : WAUZZZF5XKA074718
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 10-Jul-21
PLACE OF ACCIDENT : CAR PARK LOT NO. LO 123 AT LOR 9 GEYLANG

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SBX 8444 A

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE , CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	X
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	800.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET , AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMET COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00 500	✓
4	TO RESPRAY FRONT BUMPER, BONNET AND HINGES.	\$	2,500.00 550	✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	\$ 6,372.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SBX 8444 A

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Neu</i>	1	\$ 2,251.00	<i>+</i>	
2	FRONT BUMPER FIXING PARTS	1	\$ 407.00	<i>+</i>	
3	FRONT BUMPER SECURIN STRIP <i>Neu</i>	2	\$ 71.00	<i>+</i>	
4	FRONT BUMPER GRILLE - CENTER	1	\$ 196.00	<i>+</i>	
5	FRONT BUMPER CLOSING ELEMENT LOWER CENTRE <i>Neu</i>	1	\$ 228.00	<i>+</i>	
6	RADIATOR GRILLE <i>Neu</i>	1	\$ 2,326.00	<i>+</i>	
7	RADIATOR GRILLE SUPPORT ULTRA SENSOR LH / RH <i>Neu</i>	2	\$ 102.00	<i>+</i>	
8	RADIATOR GRILLE COVER	1	\$ 189.00	<i>+</i>	
9	FRONT AIR GUIDE GRILLE LH / RH <i>Neu</i>	2	\$ 948.00	<i>+</i>	
10	FRONT FOAM FILLIER PIECE	1	\$ 124.00	<i>+</i>	
11	FRONT BUMPER REINFORCEMENT BEAM <i>Neu</i>	1	\$ 845.00	<i>+</i>	
12	FRONT BUMPER COVER	1	\$ 127.00	<i>+</i>	
13	STICKER FOR SIGN 'CUATION'	1	\$ 14.00	<i>+</i>	
14	STICKER FOR AIR CONDITIONER <i>Neu</i>	1	\$ 8.00	<i>+</i>	
15	FRONT LOCK CARRIER BRACKET	1	\$ 137.00	<i>+</i>	
16	FRONT LOCK CARRIER SUPPORT LH / RH <i>Neu</i>	2	\$ 58.00	<i>+</i>	
17	FRONT SENSOR <i>Neu</i>	2	TBC	<i>+</i>	
18	FRONT SENSOR SEAL RING <i>Neu</i>	4	\$ 14.00	<i>+</i>	
19	BONNET <i>Dented</i>	1	\$ 3,312.00	<i>+</i>	
20	BONNET ATTACHMENT PARTS <i>Neu</i>	1	\$ 123.00	<i>+</i>	
SUB TOTAL SPARE PARTS			\$ 11,480.00		

✓ 2649.60

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SBX 8444 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	BONNET HINGE LH/ RH <i>new</i>	2	\$ 838.00	<i>x</i>
22	BONNET IMPACT PROTECTION LH / RH <i>new</i>	2	\$ 56.00	<i>✓</i> 43.68
23	BONNET NOISE INSULATION	1	\$ 343.00	<i>+</i>
24	BONNET STRICKER LH / RH	2	\$ 100.00	<i>+</i>
25	BONNET LID LOCK	2	\$ 427.00	<i>+</i>
26	BONNET RELEASE CABLE	1	\$ 58.00	<i>+</i>
27	BONNET LOCK COVER	1	\$ 10.00	<i>+</i>
28	BONNET BOWDEN CABLE CENTER <i>new</i>	1	\$ 58.00	<i>+</i>
29	BONNET RELEASE LEVER	1	\$ 14.00	<i>+</i>
30	LED HEADLIGHT LH / RH <i>new</i>	2	\$ 15,804.00	<i>x</i>
31	LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM <i>new</i>	2	\$ 396.00	<i>+</i>
32	CORRUGATED PIPE FOR HEADLIGHT WASHER SYSTEM	1	\$ 86.00	<i>+</i>
33	RADIATOR AIR GUIDE LH <i>new</i>	1	\$ 32.00	<i>+</i>
34	RADIATOR AIR GUIDE RH	1	\$ 31.00	<i>+</i>
35	RADIATOR AIR GUIDE LH OUTER	1	\$ 16.00	<i>+</i>
36	RADIATOR AIR GUIDE RH OUTER	1	\$ 16.00	<i>+</i>
37	RADIATOR AIR GUIDE RH UPPER	1	\$ 16.00	<i>+</i>
38	RADIATOR AIR GUIDE RH LOWER	1	\$ 22.00	<i>+</i>
39	CAR PLATE NO. <i>new</i>	S/N	\$ 60.00	<i>x</i>
40	SUNDRIES <i>? nec</i>		\$ 350.00	<i>? 22</i>
TOTAL SPARE PARTS		:	\$ 30,213.00	
TOTAL LABOUR CHARGES		:	\$ 6,372.00	
GRAND TOTAL		:	\$ 36,585.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adnan Lij
SURVEYED DATE : 18/08/21
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised , 03 Days .

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT