

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

26-Oct-21

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1265 E

1 pc	Tailgate lower garnish	\$	362.61 <i>Ry</i>
1 pc	Tailgate weatherstrip	\$	276.98 <i>X yn</i>
1 pc	Tailgate Striker	\$	36.50 <i>X nu</i>
1 pc	Emblem CRDI	\$	29.40 <i>ag</i>
1 pc	Emblem Hyundai logo	\$	29.40 <i>X nu</i>
1 pc	Rear bumper	\$	811.11 <i>de</i>
1 pc	Rear bumper sponge	\$	79.20 <i>X</i>
1 pc	Rear bumper reinforcement	\$	815.64 <i>X</i>
1 pc	Rear bumper reinforcement centre	\$	79.20 <i>X</i>
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20	\$	104.40 <i>X</i>
2 pcs	Rear bumper n/s & o/s reflector	\$	107.50 <i>X</i>
		\$	2,731.94 <i>840.51</i>
	Less 20%	\$	546.39
		\$	2,185.55 <i>672.40</i>
<u>S/NETT</u>			
1 set	Rear bumper clips	\$	48.00 <i>3 one</i>
1 set	Reverse sensor	\$	280.00 <i>200 nu</i>
1 set	Tailgate stickers	\$	100.00 <i>60 nu</i>
1 set	Tailgate lower garnish clips	\$	38.00 <i>X nu 290</i>
	Sundry	\$	50.00 <i>X nu</i>
	To dismantle and replace reverse sensor; and test system	\$	80.00 <i>30</i>
	To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the end panel etc		<i>672.40</i> <i>290</i> <i>530</i>
	To putty and spray painting on the rear bumper, tailgate, tailgate lower garnish, end panel,	\$	600.00 <i>200</i>
	To apply rustproofing on the repaired and replaced panels	\$	700.00 <i>300</i>
		\$	120.00 <i>X nu</i>
		\$	4,201.55 <i>530</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Tanfahin 27495747
26/10/21 @ 1515
1/3 Resurvey after repair
02 days
Tanfahin @ the workshop