



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2205835
INV Date 20/09/2022
Reference CC4/LPC21010971/Uea3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. GBK 6290H
Insured Veh. GBA 9693L
Claim No. 21/21/21/VC05/025073
Policy No. Z21VC05007392
Accident Date 23/10/2021
Inspection Date 13/12/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: CC4/LPC21010971/Uea3q2

Date: 20/09/2022

Code: LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBA 9693L	Veh. Inspected	GBK 6290H
Policy No.	Z21VC05007392	Coverage (\$)	0.00
Claim No.	21/21/21/VC05/025073	Excess (\$)	0.00
Assign From	KENNY	Assign Date	26/10/2021

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE (M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	JTFHT02P709990474	Colour	SILVER
Odometer	27114 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	BRIDGESTONE	6 mm
L/H Front Tyre	195 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	195 R15	BRIDGESTONE	6 mm
L/H Rear Tyre	195 R15	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/10/2021	Inspection Date	13/12/2021
Survey held at	BORNEO MOTORS (S) PTE LTD 17 UBI ROAD 4 SINGAPORE 408611		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBK 6290H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN)	NECESSARY	30.00	30.00
1	REAR BUMPER COVER (SN)	DENTED / BENT	458.80	458.80
1	L/R BPR SIDE SUPPORT (SN)	NOT NECESSARY	23.60	-
1	R/R SIDE BPR RETAINER (SN)	NOT NECESSARY	23.60	-
4	REAR BUMPER BRACKET (SN)	BENT / NECESSARY	105.60	105.60
4	GROMMET SCREW (SN)	NECESSARY	8.80	8.80
1	REAR OUTER FLR MEMBER (SN)	TO REPAIR SEE LABOUR	346.40	-
1	PANEL SUB-ASSY ,BACK (SN)	DENTED	2,184.00	2,184.00
1	RR BACK DOOR W/STRIP (SN)	NECESSARY	412.60	-
1	GLAS SUB-ASSY ,BACK (SN)	NECESSARY	1,352.20	1,352.20
1	EMBLEM (SN)	NECESSARY	72.20	72.20
1	PLATE LUGGAGE (SN)	NECESSARY	49.10	49.10
2	SIKA182010 SIKA TACK GO (BLA) (SN)	NECESSARY	216.00	216.00
1	SIKA 207 G+P ADHESIVE PRIMER (SN)	NECESSARY	200.00	200.00
1	TAILGATE STICKER -70KM/H (SN)	NECESSARY	18.00	18.00
2	PT SENSOR FOR HIACE (SN)	NECESSARY	56.40	56.40
			5,557.30	4,751.10
LABOUR				
DRILL HOLE & INSTALL REAR REVERSE SENSOR .			180.00	180.00
CHECK LIGHTING & CONDUCT WATER LEAK TEST.			180.00	180.00
SUPPLY SEALANT -TAILGATE.			60.00	60.00
TRANSFER & INSTALL COMPONENTS TO NEW TAILGATE.			360.00	360.00
REPLACE & INSTALL REAR WINDSCREEN GLASS .			495.00	462.00
TO RESET ECU AND REPROGRAMME.			180.00	180.00
REPLACE REAR ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS .INCLUSIVE OF THE REPAIR OF REAR OUTER FLR MEMBER.			2,880.00	1,800.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RESPRAY JOB ON REAR ACCIDENT AFFECTED AREAS .		2,360.00	1,770.00
			6,695.00	4,992.00
	GRAND TOTAL		12,252.30	9,743.10
RECOMMENDED COST OF REPAIRS				9,743.10

Report Ref No. CC4/LPC21010971/Uea3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBK 6290H

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBK 6290H

RE-INSPECTION

