



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

| | | | | | | | |
|------------------------|--|--|--------------------|--|---|--|--|
| Account Details | | | Account No. | | Customer Details | | |
| THIRD PARTY CLAIM | | | S1000020 / TPCLAIM | | M/S Standard Air-Con Pte Ltd 152 Beach Road #14-03 Gateway East Singapore 189721 | | |
| | | | Document No. | | | | |
| | | | 0 | | | | |
| | | | Document Date | | | | |
| | | | 26/10/2021 | | | | |

| Year | Model | Variant | Reg. Date | Reg. No. | Kilometers | Wip No. | Order No. / Remarks |
|------|---------|----------|------------|----------|------------|---------|---------------------|
| 2020 | KDH201R | SBMDY S5 | 29/09/2020 | GBK6290H | 0 | 21336 | 67/DS/GBK6290H |

| Chassis No. | Engine No. | Terms | SA / Counter | Vehicle In | Collected On |
|-------------------|------------|-------|--------------|------------|-----------------|
| JTFHT02P709990474 | 1KDB048411 | 60 | Sam San Joi | --/--/---- | 0.00 --/--/---- |

| L | Cd | Job/Parts Description | Qty | Unit Price | Disc % | Amount |
|----|----|--|------|------------|--------|---------|
| 1 | Z | BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-GBA9693L ACC DATE:23/10/2021 DRIVE IN:25/10/2021 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON: | | | | 30.00 |
| 2 | B | BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR | | | | 180.00 |
| 3 | B | BP-LAB2 CHECK LIGHTING & CONDUCT WATER LEAK TEST | | | | 180.00 |
| 4 | Z | BP-SLANT SUPPLY SEALANT (NETT)-TAILGATE | | | | 60.00 |
| 5 | B | BP-LAB2 TRANSFER & INSTALL COMPONENTS TO NEW TAILGATE | | | | 360.00 |
| 6 | B | BP-LAB2 REPLACE & INSTALL REAR WINDSCREEN GLASS | | | | 495.00 |
| 7 | B | BP-LAB2 TAILGATE STICKER-70KM/H | | | | 18.00 |
| 8 | S | BP-SUBLET TO RESET ECU AND REPROGRAMME | | | | 180.00 |
| 9 | B | BP-LAB2 REPLACE REAR ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS | | | | 2880.00 |
| 10 | B | BP-RES2 RESPRAY JOB ON REAR ACCIDENT AFFECTED AREAS | | | | 2360.00 |
| 11 | 1 | TREVSE-FMS02 ZGE 2 PT SENSOR FOR HIACE | 1.00 | 56.40 | | 56.40 |
| 12 | 2 | T52159-26470 REAR BUMPER COVER, | 1.00 | 458.80 | | 458.80 |

| | | | |
|---|---------------------------------------|--|------------|
| For & on behalf of Borneo Motors (Singapore) Pte Ltd | Customer's Signature | Charge Summary | Total |
| | Please acknowledge receipt of vehicle | Parts Labour Sublet Lubrication/Fluid Others | Less |
| | | | Amount Due |

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

| | | | | | | | |
|------------------------|--|--|--------------------|--|---|--|--|
| Account Details | | | Account No. | | Customer Details | | |
| THIRD PARTY CLAIM | | | S1000020 / TPCLAIM | | M/S Standard Air-Con Pte Ltd 152 Beach Road #14-03 Gateway East Singapore 189721 | | |
| | | | Document No. | | | | |
| | | | 0 | | | | |
| | | | Document Date | | | | |
| | | | 26/10/2021 | | | | |

| Year | Model | Variant | Reg. Date | Reg. No. | Kilometers | Wip No. | Order No. / Remarks |
|------|---------|----------|------------|----------|------------|---------|---------------------|
| 2020 | KDH201R | SBMDY S5 | 29/09/2020 | GBK6290H | 0 | 21336 | 67/DS/GBK6290H |

| Chassis No. | Engine No. | Terms | SA / Counter | Vehicle In | Collected On |
|-------------------|------------|-------|--------------|------------|-----------------|
| JTFHT02P709990474 | 1KDB048411 | 60 | Sam San Joi | --/--/---- | 0.00 --/--/---- |

| L | Cd | Job/Parts Description | Qty | Unit Price | Disc % | Amount |
|----|----|--|------|------------|--------|---------|
| 13 | 3 | T52158-26010 L/R BPR SIDE SUPPORT, | 1.00 | 23.60 | | 23.60 |
| 14 | 4 | T52157-26010 R/R SIDE BPR RETAINER, | 1.00 | 23.60 | | 23.60 |
| 15 | 5 | T58385-26070 REAR BUMPER BRACKET, | 4.00 | 26.40 | | 105.60 |
| 16 | 6 | T90189-06228 GROMMET SCREW | 4.00 | 2.20 | | 8.80 |
| 17 | 7 | T57069-26120 REAR OUTER FLR MEMBER, | 1.00 | 346.40 | | 346.40 |
| 18 | 8 | T67005-26L50 PANEL SUB-ASSY, BACK | 1.00 | 2184.00 | | 2184.00 |
| 19 | 9 | T67881-26073 RR BACK DOOR W/STRIP, | 1.00 | 412.60 | | 412.60 |
| 20 | 0 | T68105-26151 GLASS SUB-ASSY, BACK | 1.00 | 1352.20 | | 1352.20 |
| 21 | 1 | T90975-02064 EMBLEM | 1.00 | 72.20 | | 72.20 |
| 22 | 2 | T75441-26281 PLATE,LUGGAGE | 1.00 | 49.10 | | 49.10 |
| 23 | 3 | T21000-20 SIKA 182010 SIKA TACK GO! (BLA | 2.00 | 108.00 | | 216.00 |
| 24 | 4 | T21000-22 SIKA 207. G+P ADHESIVE PRIMER | 1.00 | 200.00 | | 200.00 |

| | | | | |
|---|---------------------------------------|---|-------------------------------|-----------|
| For & on behalf of Borneo Motors (Singapore) Pte Ltd | Customer's Signature | Charge Summary | Total | 12,252.30 |
| | Please acknowledge receipt of vehicle | Parts 5,509.30 Labour 6,563.00 Sublet 180.00 Lubrication/Fluid 0.00 Others 0.00 | GST 7.00% 857.66 Less 0.00 | |
| | | | Amount Due | 13,109.96 |

Customer Copy