



# Borneo Motors

Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

17 UBI ROAD 4

SINGAPORE 408611, Tel no : 6631 1188



# TOYOTA

*not Admit  
dharanaj.  
Tolonglah sekiranya  
5- days  
13/11/21*

## ESTIMATE

<b>Account Details</b>		<b>Account No.</b>	<b>Customer Details</b>	
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia		S1000007 / ICLP1	M/S Standard Air-Con Pte Ltd 152 Beach Road #14-03 Gateway East Singapore 189721	
		<b>Document No.</b>		
		0		
		<b>Document Date</b>		
		16/11/2021		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	KDH201R	SBMDY S5	29/09/2020	GBK6290H	0	21336	67/DS/GBK6290H
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTFHT02P709990474	1KDB048411	60	Sam San Joi	-/-/---	0.00	-/-/---	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-GBA9693L ACC DATE:23/10/2021 DRIVE IN:25/10/2021 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				30.00
2	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR				180.00
3	B	BP-LAB2 CHECK LIGHTING & CONDUCT WATER LEAK TEST				180.00
4	Z	BP-SLANT SUPPLY SEALANT (NETT)-TAILGATE				60.00
5	B	BP-LAB2 TRANSFER & INSTALL COMPONENTS TO NEW TAILGATE				360.00
6	B	BP-LAB2 REPLACE & INSTALL REAR WINDSCREEN GLASS				495.00
7	B	BP-LAB2 TAILGATE STICKER-70KM/H				18.00
8	S	BP-SUBLET TO RESET ECU AND REPROGRAMME				180.00
9	B	BP-LAB2 REPLACE REAR ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS				2880.00
10	B	BP-RES2 RESPRAY JOB ON REAR ACCIDENT AFFECTED AREAS				2360.00
11	1	TREVSE-FMS02 ZGE 2 PT SENSOR FOR HIACE	1.00	56.40		56.40
12	2	T52159-26470 REAR BUMPER COVER,	1.00	458.80		458.80

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less  Amount Due

Customer Copy



# Borneo Motors

Inchcape

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
17 UBI ROAD 4  
SINGAPORE 408611, Tel no.: 6631 1188



# TOYOTA

## ESTIMATE

Account Details		Account No.		Customer Details					
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia		S1000007 / ICLP11		M/S Standard Air-Con Pte Ltd 152 Beach Road #14-03 Gateway East Singapore 189721					
		Document No.							
		0							
		Document Date							
		16/11/2021							
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2020	KDH201R	SBMDY S5	29/09/2020	GBK6290H	0	21336	67/DS/GBK6290H		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTFHT02P709990474		1KDB048411	60	Sam San Joi	--/--/----		0.00 --/--/---- 0.00		
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount	
13	3	T52158-26010	L/R BPR SIDE SUPPORT,			1.00	23.60	?	23.60
14	4	T52157-26010	R/R SIDE BPR RETAINER,			1.00	23.60	?	23.60
15	5	T58385-26070	REAR BUMPER BRACKET,			4.00	26.40	---	105.60
16	6	T90189-06228	GROMMET SCREW			4.00	2.20	---	8.80
17	7	T57069-26120	REAR OUTER FLR MEMBER,			1.00	346.40	X	346.40
18	8	T67005-26L50	PANEL SUB-ASSY, BACK			1.00	2184.00	X	2184.00
19	9	T67881-26073	RR BACK DOOR W/STRIP,			1.00	412.60	X	412.60
20	0	T68105-26151	GLASS SUB-ASSY, BACK			1.00	1352.20	---	1352.20
21	1	T90975-02064	EMBLEM			1.00	72.20	---	72.20
22	2	T75441-26281	PLATE,LUGGAGE			1.00	49.10	---	49.10
23	3	T21000-20	SIKA 182010 SIKA TACK GO! (BLA			2.00	108.00	---	216.00
24	4	T21000-22	SIKA 207. G+P ADHESIVE PRIMER			1.00	200.00	---	200.00
For & on behalf of		<div style="border: 1px solid blue; padding: 5px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>To resurvey before/after spray painting</li> <li>To display damaged part(s) during resurvey</li> <li>Parts prices are subject to confirmation</li> <li>Third party survey is on a "Without Prejudice" basis</li> <li>No illegal modification(s) is allowed</li> <li>Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> </div>			Charge Summary		Total	12,252.30	
Borneo Motors (Singapore) Pte Ltd					Customer's Signature				GST 7.00%
		Please acknowledge receipt of vehicle		Parts	5,509.30	Less	0.00		
		Date:		Labour	6,563.00				
				Sublet	180.00				
				Lubrication/Fluid	0.00				
				Others	0.00	Amount Due	13,109.96		

Customer Copy