



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2200562
3 ANSON ROAD #16-00	INV Date	27/01/2022
SPRINGLEAF TOWER	Reference	CC3/CTI21010973/R1rs3q2
SINGAPORE 079909	Code	CTI

PROFESSIONAL SERVICE FEE

Vehicle No.	SHC 7280B
Insured Veh.	GBJ 8572L
Claim No.	SNM21D206096/LKKDS
Policy No.	DMCVSNW00114342100
Accident Date	22/10/2021
Inspection Date	25/10/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Ref: CC3/CTI21010973/R1rs3q2

Date: 27/01/2022

Code: CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBJ 8572L	Veh. Inspected	SHC 7280B
Policy No.	DMCVSNW00114342100	Coverage (\$)	0.00
Claim No.	SNM21D206096/LKKDS	Excess (\$)	0.00
Assign From		Assign Date	25/10/2021

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS HYBRID 1.8 CVT	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU003562722	Colour	YELLOW
Odometer	574033 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	WEST LAKE	6 mm
L/H Front Tyre	195/65 R15	WEST LAKE	6 mm
R/H Rear Tyre	195/65 R15	WEST LAKE	6 mm
L/H Rear Tyre	195/65 R15	WEST LAKE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/10/2021	Inspection Date	25/10/2021
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7280B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	458.60	458.60
1	REAR BUMPER LOWER COVER	DEFORMED	552.60	552.60
1	REAR BUMPER REINFORCEMENT	BENT	318.80	318.80
1	REAR TRUNK LID PRIUS	NECESSARY	52.40	52.40
1	REAR TRUNK LID HYBRID	NECESSARY	52.90	52.90
1	REAR BUMPER TOW COVER	SCRATCHED	82.70	82.70
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
	LESS 25% DISCOUNT		-385.00	-385.00
			1,155.00	1,155.00
<u>SPECIAL NETT ITEMS</u>				
1	BUMPER MAT (SN)	NOT NECESSARY	50.00	-
1	REAR TRUNK CONFORT APP (SN)	NECESSARY	40.00	40.00
1	REAR TRUNK COMFORTDELGRO & TEL NO (SN)	NECESSARY	60.00	60.00
1	BUMPER ADVERTISEMENT (SN)	NECESSARY	50.00	50.00
1	BUMPER REVERSE SENSOR (SN)	NOT NECESSARY	135.70	-
			335.70	150.00
<u>LABOUR</u>				
	PANEL BEATING.		570.00	350.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	CHECK WIRING & LIGHTING.	NOT NECESSARY	60.00	-
	REMOVE/REFIX REVERSE SENSOR .		60.00	40.00
			1,290.00	890.00
GRAND TOTAL			2,780.70	2,195.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,750.00

Report Ref No. CC3/CTI21010973/R1rs3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 7280B

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 7280B

RE-INSPECTION

