

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD9953A***Not Notified*  
*Rebody B4 paint***AAD2110-**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**SHD9953A**

JTDKB3FU703093449

TOYOTA

PRIUS GEN 4

22/10/2021

**CHINA**

11/01/2021

- PART**
- 1 COVER, REAR BUMPER
  - 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
  - 1 GUARD, REAR BUMPER, CENTER
  - 1 COVER, REAR BUMPER, LOWER
  - 1 RETAINER, REAR BUMPER SIDE, LH
  - 1 RETAINER, REAR BUMPER SIDE, RH
  - 1 PANEL SUB-ASSY, BODY LOWER BACK

<b>LIST</b>	
\$	R 485.60 X
\$	R 332.70 X
\$	Red/W 374.50 ✓
\$	SL 22.00 X
\$	SL 132.60 X
\$	SL 132.60 X
\$	R 651.00 ✓
<b>TOTAL</b>	<b>\$ 2,131.00</b>
<b>25%</b>	<b>\$ 532.75</b>
	<b>\$ 1,598.25</b>

**Special Nett**

- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
  - 1 REAR NUMBER PLATE WITH MOULDING
  - 1 BUMPER CENTRE GUARD CLIP
  - 1 REAR BUMPER PROTECTOR
  - 1 REAR BUMPER RETAINER CLIP

\$	SL 700.00 X
\$	nn 85.00 X
\$	SL 200.00 X
\$	nn 80.00 X
\$	SL 180.00 X
\$	nn 75.00 X
<b>TOTAL</b>	<b>\$ 1,320.00</b>

**TOTAL PARTS \$ 2,918.25****LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas. \$ nn 240.00 X

**Trans-cab Auto Services Pte Ltd**

AAD2110-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9953A

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair. \$ *nn* 380.00 *X*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same \$ 2,000.00 *100%*

To transfer of rear end panel fittings, attachment to facilitate bodywork repair. \$ *nn* 380.00 *X*

Putty And Spray Painting Of The Affected Portion. \$ 1,600.00 *22%*

To Remove And Refit Rear Big & Small W/Screen Glass To Facilitate Bodywork Repair. \$ *nn* 300.00 *X*

To reinstall rear bumper parking sensor. \$ *nn* 170.00 *X*

To Check Electrical Lighting Concerned. \$ *nn* 170.00 *X*

**TOTAL \$ 5,240.00**

**Over All Total \$ 8,158.25**

**(PART-BY-PART) Repair Days**

*20 Days*  
*1 1/2 day*

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: