

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21010980/T1VF3Q2
Date: 26/11/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210014016
Claimant Vehicle No :	FBP4200E	Insured Vehicle No :	SME903P
Date of Loss:	16/10/2021	Nature of Claim:	TP
		Claim No:	1329984485SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBP4200E		
Make & Model:	SYM JOYRIDE 200 I, 175cc	Engine No:	MG502516
Reg. Date:	01/04/2019 (Man. Year: 2019)	Chassis No:	RFGLFA501KSA02533
Colour:	Grey	Odometer:	25727 km
Engine Capacity:	175 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	110/90 R13	Rear Tyre Size:	130/70 R12
Front Left Side:	Maxxis 5 mm	Rear Left Side:	Maxxis 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 27/10/2021

Date Inspected: 27/10/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Wing Fuat Trading Co
Blk 3020A Ubi Road 1, #01-37
Singapore 408714

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE:\$8,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER WHEEL GUARD	Cut	0.00 F	*- F
2	1		*FRONT FORK ASSY	*Check	0.00 F	*- F
3	1		*FRONT HEADLAMP	Cut	0.00 F	*- F
4	1		*FRONT HEADLAMP FAIRING	Cut	0.00 F	*- F
5	1		*FRONT WING MIRROR	Cut	0.00 F	*- F
6	1		*FRONT RH SIGNAL LAMP	Cut	0.00 F	*- F
7	1		*HANDLE BAR	*Check	0.00 F	*- F
8	1		*HAND BRAKE LEVER	Cut	0.00 F	*- F
9	1		*SIDE FAIRING	Cut	0.00 F	*- F
10	1		*SIDE FAIRING TOP GARNISH INNER	Cut	0.00 F	*- F
11	1		*SIDE FAIRING INNER GARNISH	Cut	0.00 F	*- F
12	1		*SIDE FAIRING LOWER GARNISH	Cut	0.00 F	*- F
13	1		*REAR FAIRING	Cracked	0.00 F	*- F
14	1		*FLOORBOARD LOWER GARNISH	Cut	0.00 F	*- F
15	1		*FLOORBOARD UPPER GARNISH	*Check	0.00 F	*- F
16	1		*EXHAUST MUFFLER HEAT SHIELD	Cut	0.00 F	*- F
17	1		*REAR TAILLAMP	*Check	0.00 F	*- F
18	1		*REAR BOX	Cut	0.00 F	*- F
19	1		*REAR BOX BRACKET	*Check	0.00 F	*- F
20	1		*EMBLEM	Necessary	0.00 F	*- F
21	1		*STICKER	Necessary	0.00 F	*- F
22	1		*PILLION HANDLE GRIP	Cut	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >