

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms China Taiping Insurance (Singapore) Pte Ltd
Date: 22/10/2021

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO: SLL224R

CHASSIS NO : RU31223571

MAKE / MODEL : Honda Vezel Hybrid 1.5X AUTO

DATE OF ACCIDENT: 18/10/2021

YOUR INSURED VEHICLE NUMBER: SLV8650M

MILEAGE: 273164 km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>	
1	Rear tailgate / <i>nn</i>	1PC	\$ 1,450.00	\$ 1,450.00	953 /
2	Rear tailgate Vezel emblem / <i>nn</i>	1PC	\$ 86.80	\$ 86.80	/
3	Rear tailgate Honda emblem X <i>nn</i>	1PC	\$ 81.30	\$ 81.30	
4	Rear tailgate HYBRID emblem / <i>nn</i>	1PC	\$ 84.00	\$ 84.00	/
5	Rear tailgate windscreen moulding / <i>nn</i>	1PC	\$ 195.00	\$ 195.00	/
6	Rear tailgate weatherstrip X <i>nn</i>	1PC	\$ 155.00	\$ 155.00	
7	Rear tailgate lock X <i>nn</i>	1PC	\$ 550.00	\$ 550.00	
8	Rear end panel ? X <i>R</i>	1PC	\$ 830.00	\$ 830.00	
9	Rear end panel top garnish X <i>nn</i>	1PC	\$ 155.00	\$ 155.00	
10	Rear bumper / <i>CRV</i>	1PC	\$ 955.00	\$ 955.00	762 /
11	Rear spare tyre panel X <i>nn</i>	1PC	\$ 2,000.00	\$ 2,000.00	
12	Rear spare tyre luggage tray X <i>nn</i>	1PC	\$ 480.00	\$ 480.00	
LIST TOTAL S\$:				\$ 7,022.10	2080.80
20.00% DISCOUNT S\$:				\$ 1,404.42	-20%
Total				\$ 5,617.68	1664.64

SPECIAL NETT

1	Rear bumper clips / <i>nn</i>	1 SET	\$ 180.00	30
2	Rear end panel top garnish clips X <i>nn</i>	1 SET	\$ 80.00	
3	Reverse sensor / <i>Sharked</i>	1PC	\$ 250.00	200
5	Windscreen sealant / <i>nn</i>	1PC	\$ 200.00	40
Special Nett Total S\$:			\$ 710.00	270

LABOUR CHARGES

- | | | | |
|---|---|-------------|-----|
| 1 | To labour charge for removing rear tailgate, rear end panel, rear bumper out to facilitate repairs and replacement of damaged parts. Also include cutting out and welding of replacement spare tyre panel | \$ 1,200.00 | 400 |
| 2 | To respray rear tailgate, rear bumper, end panel and spare tyre panel | \$ 1,000.00 | 440 |
| 3 | To remove and install rear tailgate glass | \$ 160.00 | 50 |
| 4 | To check wiring system | \$ 100.00 | 30 |
| 5 | To conduct a standard of opening procedures post repairs scan test as a requirements upon completion of collision repairs | \$ 300.00 | X |
| 6 | To deactivate and active high voltage hybrid battery as a safety precautions | \$ 300.00 | X |

LABOUR TOTAL S\$:	\$	3,060.00
TOTAL S\$:	\$	9,387.68
7% GST	\$	657.14
GRAND TOTAL S\$:	\$	<u>10,044.82</u>

920

Steve (LKK)
27/10/21, 10.30am

WHL PL
L/S
My 112 Sy
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for no resurvey
- Parts prices are a true & fair representation
- Third party survey is not a basis for insurance claim
- No illegal modification
- Supplementary information should be provided
- Is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

P - 1664.64
N - 270
L - 920
2854.64
L/S - 2283.71
= 2300