

Trident Auto Service Centre Pte Ltd

8 Kaki Bukit Ave 4, #02-44

Premier @ Kaki Bukit (Gate 1)

Singapore 415875

Tel: 63441918

Date : 25/10/2021

Vehicle : SMX4920M

Make/Model : Honda Fit Hybrid

ORD : 2021

Chassis : GK31343809

ODO : 68963

ACC Date : 23/10/2021

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Estimate

S/N	Qty	Description & Specification	Amount S\$
-----	-----	-----------------------------	------------

List Items

1	1	Rear tailgate
2	1	Rear tailgate dampers
3	1	Rear tailgate inner trim board
4	1	Rear tailgate lock
5	1	Rear tailgate rubber
6	1	Rear tailgate "FIT" emblem
7	1	Rear end panel
8	1	Rear end panel inner garnish
9	1	Rear bumper

Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$1,214.60
 \$261.00
 \$314.50
 \$176.50
 \$121.30
 \$68.50
 \$658.70
 \$165.70
 \$628.60

2136
20% 1708.80

Total \$3,609.40

Less 25% \$902.35

List Total \$2,707.05 2887.52

S/Nett Items

1	1 set	Rear windscreen sealant
2	1 set	Rear "PRIVATE HIRE" sticker
3	1 set	Reverse sensor

500 \$80.00
 30 net \$45.00
 200 net \$350.00
 S/Nett Total \$475.00 280

Labour

1	To replace Rear tailgate, to repair and re-align on all accident affected areas
2	To putty and respray on accident portion
3	To check wiring

1708.80

280

1030

3018.80

500 \$600.00
 500 \$600.00
 30 \$80.00 1030

Labour Total \$1,280.00

Grand Total \$4,462.05 4642.52

Trident Auto Service Centre Pte Ltd

415875
 2400
 3 days

Taiping 9749 5749
 WP' 27/10/21 R 315pm
 4/5 Resurvey after repair.
 Taiping C/Khanbawun.
 3 days