

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD9054U****AAD2110-**

*Not Notified*  
*Return By pain*  
*83676-33*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**26 OCT 2021****SHD9054U**

JTDKB3FU803076062

TOYOTA

PRIUS

25/10/2021

Tokio

01/11/2018

**PART****LIST**

1	PANEL SUB-ASSY, FRONT DOOR, RH	\$	<i>R</i> 1,300.70	✓
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH	\$	<i>cm</i> 193.50	✓
1	HANDLE ASSY, FRONT DOOR, OUTSIDE RH	\$	<i>cm</i> 390.60	✓
1	HINGE ASSY, FRONT DOOR, LOWER RH	\$	<i>n</i> 110.60	X
1	HINGE ASSY, FRONT DOOR, UPPER RH	\$	<i>n</i> 97.50	✓
1	TAPE, BLACK OUT, NO.1 FRT RH	\$	<i>n</i> 13.30	✓
1	TAPE, BLACK OUT, NO.2 FRT RH	\$	<i>n</i> 43.50	✓
1	TAPE, BLACK OUT, NO.3 FRT RH	\$	<i>n</i> 26.30	✓
1	MOTOR ASSY, POWER WINDOW REGULATOR, FRT RH	\$	<i>n</i> 926.00	X
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH	\$	<i>n</i> 238.30	X
1	WEATHERSTRIP, FRONT DOOR, RH	\$	<i>n</i> 231.30	X
1	PANEL SUB-ASSY, REAR DOOR, RH	\$	<i>R</i> 1,294.90	✓
1	HANDLE ASSY, REAR DOOR OUTSIDE, RH	\$	<i>n</i> 97.40	X
1	FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, RH	\$	<i>n</i> 193.50	X
1	HINGE ASSY, REAR DOOR, LOWER RH	\$	<i>n</i> 87.10	X
1	HINGE ASSY, REAR DOOR, UPPER LH	\$	<i>n</i> 98.90	X
1	TAPE, BLACK OUT, NO.1 REAR RH	\$	<i>n</i> 21.90	✓
1	TAPE, BLACK OUT, NO.2 REAR RH	\$	<i>n</i> 34.90	✓
1	TAPE, BLACK OUT, NO.3 REAR RH	\$	<i>n</i> 15.40	✓
1	MOTOR ASSY, POWER WINDOW REGULATOR, REAR RH	\$	<i>n</i> 926.00	X
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH	\$	<i>n</i> 206.70	X
1	WEATHERSTRIP, REAR DOOR, RH	\$	<i>n</i> 180.10	✓
<b>TOTAL</b>		<b>\$</b>	<b>6,728.40</b>	
<b>25%</b>		<b>\$</b>	<b>1,682.10</b>	
		<b>\$</b>	<b>5,046.30</b>	

**Special Nett**

1	CLIP(FOR FRONT DOOR TRIM BOARD)	\$	<i>n</i> 65.00	X
---	---------------------------------	----	----------------	---

**Trans-cab Auto Services Pte Ltd**

AAD2110-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD9054U**

- 1 CLIP(FOR REAR DOOR TRIM BOARD)
- 1 REAR DOOR STICKER "6555-3333"
- 1 FRT DOOR STICKER 'TRANSCAB'

\$	nn	65.00	X
\$	nn	100.00	6000
\$	nn	100.00	6000
<b>TOTAL</b>	<b>\$</b>	<b>330.00</b>	

**TOTAL PARTS \$ 5,376.30**

**LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	600
Putty And Spray Painting Of The Affected Portion.	\$	1,800.00	4400
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	200
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,800.00	4000
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of rear fender panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X
<b>TOTAL</b>	<b>\$</b>	<b>4,790.00</b>	

**Over All Total \$ 10,166.30**

**(PART-BY-PART) Repair Days****20-Days****3 days**

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: