

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD9054U****AAD2110-***Not Notified  
Murray B&Pain*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**26 OCT 2021****SHD9054U**

JTDKB3FU803076062

TOYOTA

PRIUS

25/10/2021

Tokio

01/11/2018

| PART                                            | LIST                 |   |
|-------------------------------------------------|----------------------|---|
| 1 PANEL SUB-ASSY, FRONT DOOR, RH                | \$ <i>R</i> 1,300.70 | ✓ |
| 1 FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH | \$ <i>cm</i> 193.50  | ✓ |
| 1 HANDLE ASSY, FRONT DOOR, OUTSIDE RH           | \$ <i>cm</i> 390.60  | ✓ |
| 1 HINGE ASSY, FRONT DOOR, LOWER RH              | \$ <i>n</i> 110.60   | X |
| 1 HINGE ASSY, FRONT DOOR, UPPER RH              | \$ <i>n</i> 97.50    | ✓ |
| 1 TAPE, BLACK OUT, NO.1 FRT RH                  | \$ <i>n</i> 13.30    | ✓ |
| 1 TAPE, BLACK OUT, NO.2 FRT RH                  | \$ <i>n</i> 43.50    | ✓ |
| 1 TAPE, BLACK OUT, NO.3 FRT RH                  | \$ <i>n</i> 26.30    | ✓ |
| 1 MOTOR ASSY, POWER WINDOW REGULATOR, FRT RH    | \$ <i>n</i> 926.00   | X |
| 1 REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH     | \$ <i>n</i> 238.30   | X |
| 1 WEATHERSTRIP, FRONT DOOR, RH                  | \$ <i>n</i> 231.30   | ✓ |
| 1 PANEL SUB-ASSY, REAR DOOR, RH                 | \$ <i>R</i> 1,294.90 | ✓ |
| 1 HANDLE ASSY, REAR DOOR OUTSIDE, RH            | \$ <i>n</i> 97.40    | X |
| 1 FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, RH  | \$ <i>n</i> 193.50   | X |
| 1 HINGE ASSY, REAR DOOR, LOWER RH               | \$ <i>n</i> 87.10    | X |
| 1 HINGE ASSY, REAR DOOR, UPPER LH               | \$ <i>n</i> 98.90    | ✓ |
| 1 TAPE, BLACK OUT, NO.1 REAR RH                 | \$ <i>n</i> 21.90    | ✓ |
| 1 TAPE, BLACK OUT, NO.2 REAR RH                 | \$ <i>n</i> 34.90    | ✓ |
| 1 TAPE, BLACK OUT, NO.3 REAR RH                 | \$ <i>n</i> 15.40    | ✓ |
| 1 MOTOR ASSY, POWER WINDOW REGULATOR, REAR RH   | \$ <i>n</i> 926.00   | X |
| 1 REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH      | \$ <i>n</i> 206.70   | X |
| 1 WEATHERSTRIP, REAR DOOR, RH                   | \$ <i>n</i> 180.10   | ✓ |
| <b>TOTAL</b>                                    | <b>\$ 6,728.40</b>   |   |
| <b>25%</b>                                      | <b>\$ 1,682.10</b>   |   |
|                                                 | <b>\$ 5,046.30</b>   |   |

**Special Nett**

|                                   |                   |   |
|-----------------------------------|-------------------|---|
| 1 CLIP(FOR FRONT DOOR TRIM BOARD) | \$ <i>n</i> 65.00 | X |
|-----------------------------------|-------------------|---|

**Trans-cab Auto Services Pte Ltd**

AAD2110-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD9054U**

|                                  |           |                 |      |
|----------------------------------|-----------|-----------------|------|
| 1 CLIP(FOR REAR DOOR TRIM BOARD) | \$        | na 65.00        | X    |
| 1 REAR DOOR STICKER "6555-3333"  | \$        | na 100.00       | 6555 |
| 1 FRT DOOR STICKER 'TRANSCAB'    | \$        | na 100.00       | 6555 |
| <b>TOTAL</b>                     | <b>\$</b> | <b>330.00</b>   |      |
| <b>TOTAL PARTS</b>               | <b>\$</b> | <b>5,376.30</b> |      |

**LABOUR**

|                                                                                                                           |           |                  |      |
|---------------------------------------------------------------------------------------------------------------------------|-----------|------------------|------|
| To Rust-Proofing and apply undercoat Of The Affected Areas.                                                               | \$        | 250.00           | 601  |
| Putty And Spray Painting Of The Affected Portion.                                                                         | \$        | 1,800.00         | 4401 |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.                           | \$        | na 380.00        | X    |
| To Check Electrical Lighting Concerned.                                                                                   | \$        | 170.00           | 201  |
| Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same | \$        | 1,800.00         | 4001 |
| To check steering geometry and computer wheel alignment                                                                   | \$        | na 220.00        | X    |
| To transfer of rear fender panel fittings, attachment and perform water seepage test.                                     | \$        | na 170.00        | X    |
| <b>TOTAL</b>                                                                                                              | <b>\$</b> | <b>4,790.00</b>  |      |
| <b>Over All Total</b>                                                                                                     | <b>\$</b> | <b>10,166.30</b> |      |

**(PART-BY-PART) Repair Days****20 Days****3 days****LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: