

ESTIMATE OF REPAIR

Veh# : GBE9874K

Accident Date : 26/10/2021

Location : KJE (WOODLANDS) BEFORE SUNGEI TENGAH

Model:

3P: GBF3568 (LONPAC)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- To obtain final approval from Insurance Company (13/5/2016)


Acknowledged by Repairer

Signature:

Date:

S/Nos	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper <i>Defect</i>	656.20	✓	
2	1 pc	Rear bumper o/s & n/s retainer <i>on</i>	182.70	✓	
3	10 pcs	Rear bumper clips <i>for</i>		30.00	✓
4	4pcs	Rear centre bracket <i>Best</i>	80.00	✓	
5	1 pc	Rear tail-gate <i>Distorted</i> 1755	1925.90	✓	
6	1 pc	Rear tail-gate weatherstrip <i>at</i>	320.00	✓	
7	1 pc	Rear tail-gate inner trim	210.00	✓	
8	6pcs	Rear tail-gate inner trim clips <i>3 new</i>		24.00	+
9	1 pc	Rear tail-gate aluminum		400.00	+
10	80pcs	Rear tail-gate aluminum rivet		80.00	+
11	1 pc	Rear tail-gate 'TOYOTA' emblem <i>3 new</i>	82.00	✓	
12	1 pc	Rear tail-gate '70 KMPH' emblem		15.00	✓
13	1 pc	Rear tail-gate 'TOYOTA HIACE' emblem <i>new</i>	60.00	✓	
14	1 pc	Rear tail-gate moulding <i>new</i>	310.40	+	
15	6pcs	Rear tail-gate moulding clips <i>new</i>		24.00	+
16	1 pc	Rear tail-gate lock (upper) <i>Defect</i>	172.00	✓	
17	1 pc	Rear tail-gate lock (lower) <i>new</i>		+	
18	1 pc	Rear tail-gate lock actuator <i>Defect</i>	365.60	✓	
19	1 pc	Rear o/s & n/s tail lamp <i>o/s panel</i>	891.20	385	
20	1 pc	Rear end panel (outer) <i>Painted</i>	596.00	✓	
21	1 pc	Rear step panel <i>Defect</i>	310.20	✓	
22	1 pc	Rear windscreen moulding <i>3 new</i>		120.00	✓
23	1 pc	Rear windscreen sealant		80.00	60
24	1 pc	Rear reg. no. plate <i>new</i>		35.00	+
25	1set	Rear reverse sensor <i>Defect</i>		280.00	200
26	1 pc	Rear reverse camera <i>damaged</i>	300.00	✓	
		Sub-Total:	6,162.20	1388.00	0.00
			25%	0%	10%
		After Less %:	4,621.65	1388.00	0.00
		Labour			
1		To dismantle damaged parts, straighten & welding.		800.00	700
2		To spray painting.		600.00	✓
3		To remove & refit rear windscreen		140.00	120
4		To remove and replace rear reverse camera		100.00	50
5		To remove and refit rear tail gate <i>Body</i>		80.00	60
6		To remove and replace rear tail gate aluminium		80.00	40
7		To remove and refit rear floor aluminium to facilitate repair		150.00	+
8		To remove and refit rear upholstery to facilitate repair		300.00	+
9		To check wiring.		80.00	30
10		To re-seal anti-rust.		50.00	✓
11		To check and reset electrical system		200.00	+
		Sub-Total:		2,580.00	
		Total:		8,589.65	
		After less 20%:		6,871.72	

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)



Admin G
h/s 28/10/21
06 Days
Total: 6156.02
h/s: 4.9K