

ASS. REC. BY: Steve

C53/CTI 210/1003/EU43

ASSIGNMENT

From: PRS

Date:

Estimated Cost:

OP/TP/WS/TPRES/OD-RES/EVA/INV/MV

To Inspect Vehicle No:

FBE 65M

at Workshop m/s

Insured:

YN 7277C

Policy No.

DMCVSNW00123712003

Claims No.

SNM21D206048/C2

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report

Consistent? : Yes or No

SIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Cum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBE 65M

Yr Regn:

26/10/09

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make:

Yamaha R15

cc: 155 150

Colour:

Black

A/C: Insured / Std / NI / N

Sp. Reading

231942

T/Radio: Insured / Std / NI / N

Eng/No:

C/No:

ME 170P0 11920.20 182

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Locked / Burnt or

Brake: In order / Jammed / Locked / Burnt or

Mod: Nil / S/Rim / STD AIR / Rim or

Tyre Size:

F:

90/80-17

R:

190/80-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Maxxis

Front

Rear

R/Bal:

5

mm

R/Bal:

5

mm

L/Bal:

mm

L/Bal:

mm

D.O.A.

O.O.I. 27/10/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roof/Top or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	MV - & K
	Repair range 3K - 4K
	5 repair days
28/10/2021	Submit PRS.

Date/Time, File, Pass to:

: Prel. Report

28/10 TYPIST

: Final Report

Date/Time, File Return to:

Days Of Repair:

5

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

:

Site Insp (\$

)

\$ + RS \$

:

Interview (\$

)

Fuels

:

Tech. Insp (\$

)

Others

:

Welland (\$

)

TOTAL

30/10/2021

TP

Date/Time, File, Return to: