



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
LOW CHEE WEE ANDREW (LIU ZHIWEI)	Cust No/Name	KCV10073/LOW CHEE WEE ANDREW (LIU ZHIWEI)
2 JALAN TAMAN	Reg No/Reg Date	SMH324U / 09/01/201
#12-01	Date In/Mileage	/ 0
SINGAPORE 329023	Chassis No	JMAXTGK1WJZ004744
Contact No	Engine No	4B40GB3507
	Make/Model	MIT/ECLIPSE CROSS 1.5 T/C SPORTS (
	Colour/Trim	P26 ORIENT RED / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KCV10073	CRDVCH	27/10/2021/ 18:00	TLC	442 / CocoLu	16878			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1920.00
RENEW REAR DOOR RH, REPAIR REAR FENDER RH, REAR BUMPER					2 x 640			1280
SIDE SILL RH								120
E PNT88000								300.00
REMOVE & INSTALL REAR DOOR TRIMS & GLASS								
E PNT98000								2200.00
SPRAY PAINT FOR REAR DOOR RH, REAR FENDER RH, REAR BUMPER					2 x 550			1100
B WHEELALIGNMENT								120.00
To Conduct Computerize Full Wheel Alignment								30.00
M SUNDRY								
TRANSFER REAR RIGHT RIM								120
A 54900099								280.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								640.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
A 54900099								20.00
RENEW REAR UNDER CARRIAGE (photo)								
M SUNDRY								
Sundry								
M PANEL ASSY,RR DOOR,RH					1.00	942.00	00.00	942.00
M SHIELD,RR WHEEL,FR RH					1.00	126.00	00.00	126.00
M SHIELD,RR WHEEL,RR RH					1.00	38.00	00.00	38.00
M GARNISH,SIDE SILL,RH					1.00	91.00	00.00	91.00
M GARNISH,RR DOOR,RH					1.00	160.00	00.00	160.00
M MOULDING,R/DOOR PROTECT,RH					1.00	105.00	00.00	105.00
M GARNISH,QTR PANEL,RH					1.00	181.00	00.00	181.00
M GARNISH,RR DOOR SASH,FR RH					1.00	108.00	00.00	108.00
M MOULDING,RR WHEEL ARCH,RH					1.00	159.00	00.00	159.00
M WHEEL,DISC					1.00	1102.00	00.00	1102.00
M HUB ASSY,RR WHEEL					1.00	434.00	00.00	434.00
M SHOCK ABSORBER,RR SUSP					1.00	296.00	00.00	296.00
M ARM ASSY,RR SUSP,LWR					1.00	174.00	00.00	174.00
M ARM ASSY,RR SUSP TRAIL,RH					1.00	504.00	00.00	504.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI  
MOTORS

## ESTIMATE

Co Reg No : 1977014696

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
LOW CHEE WEE ANDREW (LIU ZHIWEI)	Cust No/Name KCV10073/LOW CHEE WEE ANDREW (LIU ZHIWEI)
2 JALAN TAMAN	Reg No/Reg Date SMH324U / 09/01/201
#12-01	Date In/Mileage / 0
SINGAPORE 329023	Chassis No JMAXTGK1WJZ004744
Contact No	Engine No 4B40GB3507
	Make/Model MIT/ECLIPSE CROSS 1.5 T/C SPORTS (
	Colour/Trim P26 ORIENT RED / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KCV10073	CRDVCH	27/10/2021/ 18:00	TLC	442 / CocoLu	16878			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	LINK,RR SUSP ASSIST				1.00	79.00	00.00	79.00
M	ARM ASSY,RR SUSP,UPR				1.00	131.00	00.00	131.00
M	CROSSMEMBER,RR SUSP				1.00	1198.00	00.00	1198.00
M	INSUL,RR SHOCK ABSORBER				1.00	57.00	00.00	57.00
M	LINK,R/SUSP STABILIZER BAR				1.00	107.00	00.00	107.00
M	VALVE,TIRE				1.00	173.00	00.00	173.00

Estimate

Stere (LKK)

28/10/21, 11.00am

WIL RL

P/P

My Bel Sm

5 days

LKK Auto Consultants hence notify the Repairer of the following:

To resurvey before/after spray painting

To display damaged part(s) during resurvey

Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Estimate

Steve (LKK)

28/10/21, 11.00am

WIL RL

P/P

My Bel Sm

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Confirm &amp; accepted by

Nett	11,705.00
7% GST on	819.35
<b>Total Payable</b>	<b>12,524.35</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.