

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMY3179M

AAD2110-

*NOT AUTHORIZED
RETURN BY PAID*

3265.45

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SMY3179M

JTDKB3FU303091584

TOYOTA

PRIUS **GEN 4**

25/10/2021

AIG

26/02/2021

26 OCT 2021

PART	LIST		
1 COVER, REAR BUMPER	\$	<i>Bu</i> 485.60	✓
1 REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	<i>Bu</i> 332.70	✓
1 COVER, REAR BUMPER, LOWER	\$	<i>SL</i> 22.00	X
1 GUARD, REAR BUMPER, CENTER	\$	<i>Bu</i> 374.50	✓
1 RETAINER, REAR BUMPER SIDE, LH	\$	<i>SL</i> 132.60	X
1 RETAINER, REAR BUMPER SIDE, RH	\$	<i>SL</i> 132.60	X
1 REFLECTOR ASSY, REFLEX, LH	\$	<i>SL</i> 39.00	X
1 REFLECTOR ASSY, REFLEX, RH	\$	<i>SL</i> 39.00	X
1 PANEL SUB-ASSY, BACK DOOR	\$	<i>Bu</i> 1,147.80	✓
1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$	<i>na</i> 54.60	X
1 PLATE, BACK DOOR NAME, NO.1	\$	<i>na</i> 54.60	X
1 ORNAMENT SUB-ASSY, BACK DOOR	\$	<i>na</i> 47.90	X
1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	<i>SL</i> 913.60	X
1 BOARD ASSY, BACK DOOR TRIM	\$	<i>SL</i> 259.20	X
1 WEATHERSTRIP, BACK DOOR	\$	<i>SL</i> 372.30	X
1 COVER, FLOOR UNDER, NO.1 LH	\$	<i>SL</i> 175.10	X
1 COVER, FLOOR UNDER, NO.2 RH	\$	<i>SL</i> 241.90	X
1 COVER, REAR FLOOR CTR	\$	<i>SL</i> 229.90	X
1 COVER, DECK TRIM, REAR	\$	<i>SL</i> 126.70	X
1 PANEL SUB-ASSY, BODY LOWER BACK	\$	<i>R</i> 651.00	X
1 STAY ASSY, BACK DOOR, LH	\$	<i>SL</i> 242.50	X
1 STAY ASSY, BACK DOOR, RH	\$	<i>SL</i> 242.50	X
1 HINGE ASSY, BACK DOOR, LH	\$	<i>R</i> 61.00	X
1 HINGE ASSY, BACK DOOR, RH	\$	<i>R</i> 61.00	X
TOTAL	\$	6,439.60	
25%	\$	1,609.90	
	\$	4,829.70	

Trans-cab Auto Services Pte Ltd

AAD2110-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMY3179M

Special Nett

1SET PARKING AID	\$	Sm	700.00	X
1SET REAR BUMPER CLIP	\$	na	95.00	505n-
2 WINDSCREEN SEALANT	\$	na	150.00	805n-
1 WINDSCREEN MOULDING	\$	na	200.00	—
1 WINDSCREEN INNER SPONGE SEAL	\$	na	130.00	305n-
1 REAR TAILGATE STICKER "Trans-Cab"	\$	na	80.00	X
1 REAR TAILGATE STICKER "6555-3333"	\$	na	80.00	X
1 REAR BUMPER PROTECTOR	\$	n/p	180.00	X
1SET REAR BUMPER RETAINER CLIP	\$	na	85.00	X
1 END PANEL TRIM CLIP	\$	na	65.00	X
1SET BUMPER CLIP FRT	\$	na	95.00	X
1 REAR NUMBER PLATE WITH MOULDING	\$	na	200.00	X
TOTAL	\$		2,060.00	
TOTAL PARTS	\$		6,889.70	

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$		300.00	1801
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		2,200.00	4001
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na	380.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$		180.00	601
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	na	480.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2110-**SMY3179M**

To transfer of Fender fittings, attachments and perform water seepage test.	\$	<i>nn</i>	480.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	<i>nn</i>	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i>	380.00	X
To check steering geometry and computer wheel alignment	\$	<i>nn</i>	220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	<i>nn</i>	250.00	X
Towing Fees	\$	<i>nn</i>	150.00	X
Putty And Spray Painting Of The Affected Portion.	\$		2,200.00	<i>44d</i>
To reinstall rear bumper parking sensor.	\$		170.00	<i>5d</i>
To Check Electrical Lighting Concerned.	\$		170.00	<i>2d</i>
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>nn</i>	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i>	220.00	X
To replace, refix and top up coolant for radiator	\$	<i>nn</i>	170.00	X
To lift-up / out engine with gear box and refit.	\$	<i>nn</i>	440.00	X
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	<i>nn</i>	380.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	<i>nn</i>	380.00	X
TOTAL	\$		10,290.00	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMY3179M

AAD2110-

Over All Total \$ 17,179.70

(PART-BY-PART) Repair Days

~~25~~ DAYS

4 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: