

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0883/2021/KS
DATE : 29-Oct-21
WIP : 51231

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY
YOUR INSURED VEH NO : SMH 4207 Z

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR ZHOU TOU
ADDRESS : 6 SINARAN DRIVE
SINGAPORE 307468
TELEPHONE : HP +65 91280750
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : P10487649R00
VEHICLE NO : **SJN 8600 Z**
MODEL CODE : AUDI Q5 2.0 TFSI
MODEL YEAR : 14/12/2018
ENGINE NO : DAX 0467627
CHASSIS NO : WAUZZZF5J2247760
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 27-Oct-21
PLACE OF ACCIDENT : 2 MATTAR RD, SG 387724

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NOPA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJN 8600 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION.	S/N \$ 360.00	X
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. X	\$ 1,200.00	500
3	TO RESPRAY REAR BUMPER, REAR LOWER BUMPER AND BOTH REAR WHEEL ARCH TRIMS X	\$ 3,300.00	400
4	TO CARRY OUT DIAGNOSTIC CHECK. ✓✓	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 5,052.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJN 8600 Z

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER <i>{ New</i>	1	\$ 1,907.00	+	
2	REAR BUMPER - LOWER	1	\$ 1,196.00	+	
3	REAR BUMPER SPOILER <i>OK</i>	1	\$ 866.00	✓	
4	REAR BUMPER TOWING CAP - LH <i>{ NE NEC</i>	1	\$ 48.00	+	
5	REAR BUMPER TOWING CAP - RH	1	\$ 29.00	+	
6	REAR BUMPER CLOSING ELEMENT - LH / RH <i>{</i>	2	\$ 192.00	+	
7	REAR BUMPER CHROME TRIM - LH / RH	2	\$ 474.00	+	
8	REAR BUMPER TAILLIGHT - LH / RH	2	\$ 1,398.00	+	
9	REAR BUMPER REINFORCEMENT BEAM	1	\$ 981.00	+	
10	REAR BUMPER SEAL - LH / RH	2	\$ 6.00	+	
11	REAR BUMPER WHEEL ARCH COVER - LH / RH <i>X</i>	2	\$ 1,166.00	✓	
12	SUNDRIES <i>?</i>	1	\$ 250.00	?	
TOTAL SPARE PARTS			: \$ 8,513.00		
TOTAL LABOUR CHARGES			: \$ 5,052.00		
GRAND TOTAL			: \$ 13,565.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King*
SURVEYED DATE : *02/11/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 02 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT