

BIFROST AUTO PTE LTD
 8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875
 Tel: +65 64524457
 Fax: +65 64524584
 Company Reg No: 201929175W

Shian Chan

Vehicle No: SMF5876X
 Model and make: BMW 528i
 Chassis: WBA5A52040D285255

Qty	Spare parts	Estimate	List price	2014	
1	Bonnet		\$ 2,024.70		DDU ✓
1	Bonnet RH hinge		\$ 128.10		} NDX
1	Bonnet LH hinge		\$ 128.10		
1	Bonnet lock		\$ 262.40		
1	Bonnet inner insulator		\$ 303.80		NDX
1	Front bumper		\$ 1,545.60		BRV ✓
1	Front bumper emblem		\$ 87.80	69.50	NECV
1	Front bumper RH chrome grille		\$ 117.30		} NDX
1	Front bumper LH chrome grille		\$ 117.30		
1	Front bumper top rubber seal		\$ 55.30		? NDX
1	Front bumper centre grille		\$ 284.30		} NDX
1	Front bumper RH grille		\$ 217.50		
1	Front bumper RH grille chome moulding		\$ 55.20		
1	Front bumper RH fog lamp assy		\$ 351.70	295.00	BRV ✓
1	Front bumper reinforcement		\$ 684.75		DDU ✓
1	Front bumper reinforcement RH bracket		\$ 86.70		DDU ✓
1	Front bumper RH inner sponge		\$ 76.00		? BRV ✓
1	Front bumper lower beam		\$ 184.80		NSX
1	Front bumper RH brake duct		\$ 87.50		NSX
1	Front bumper lower cover		\$ 173.80		BRV ✓
1	Front bumper RH side retainer		\$ 67.50		} NECV
1	Front bumper LH side retainer		\$ 67.50		
1	Front bumper RH side distance sensor		\$ 238.05		? SCU
4	Front bumper distance sensor holders		\$ 130.40		NECV
1	Front RH fender		\$ 855.20		DDU ✓
1	Front RH fender splash shield		\$ 178.40		TJV ✓
1	RH headlamp assy		\$ 3,000.00		BRV ✓
1	RH headlamp nozzle cover		\$ 32.10		DLV ✓
1	RH headlamp nozzle		\$ 168.70		? MIS
1	RH headlamp lower bracket		\$ 155.35		? BRV ✓
1	LH headlamp assy * NN		\$ 3,000.00	X \$ 3,000.00	BRV ✓
1	LH headlamp lower bracket		\$ 155.35		NDX
1	Front top centre panel		\$ 202.50		DDU ✓
1	Support panel		\$ 445.80	355.00	BRV ✓
1	Aircon condenser		\$ 1,018.90	NDX	DDU ✓
1	Radiator assy		\$ 1,783.00		NDX
1	Front RH radiator		\$ 855.10		} NDX
1	Front RH radiator air duct		\$ 166.30		
1	Wiper tank		\$ 156.52		BRV ✓
1	Front RH lower arm		\$ 591.30	412.50	BTV ✓
1	Front RH shock absorber		\$ 520.40		BTV ✓
1	Front RH knuckle arm		\$ 723.10	599.70	BTV ✓

- 1 Front RH wheel bearing
- 1 Front RH control arm
- 1 Steering rack and pinion
- 1 Front RH door

\$ 402.15	468.70	} JMV ✓ ? BT ✓ BT ✓ DD ✓
\$ 234.06	492.80	
\$ 3286.25	4,610.90	
\$ 1,286.70	1,668.95	

	17,567.43	\$	28,725.47
@5%	1028.37	-5% \$	1,436.27
	16,689.06	\$	27,289.20

Qty Spare parts

- 1 Front RH sport rim
- 1 Front RH tyre
- 1 Brake fluid
- 1set Front bumper clips
- 1set Front RH fender splash shield clips
- 1 Radiator coolant

		Special Nett price	
\$ 800.00	+1,200.00	CUT ✓	
\$	-380.00	NDX	
\$	70.00	NNX	
\$ 30.00	-80.00	NEC	
\$ 30.00	70.00	NECU	
\$	85.00	NNX	
	860.00		

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts.
To panel beating, cut / weld and re-align all affected panels

\$ 800.00	-1,400.00	✓
-----------	-----------	---

Spray painting on affected panels

\$ 800.00	+1,500.00	✓
-----------	-----------	---

Check all wiring and all lighting system

\$	80.00	NNX
----	-------	-----

Apply rust coating chemical on affected panels

\$	50.00	NNX
----	-------	-----

Remove and replace radiator, pipes and hoses to assist repair. To refill coolant

\$	200.00	NNX
----	--------	-----

Remove and replace aircon condenser, hoses and pipes to assist repair. To refill gas

\$ 120.00	200.00	NNX
----------------------	--------	-----

Remove and replace front RH radiator, pipes and hoses to assist repair

\$	-180.00	NNX
----	---------	-----

Remove and replace front RH undercarriage parts to assist repair

\$ 250.00	550.00	✓
-----------	--------	---

Conduct and adjust wheel alignment system

\$ 60.00	-120.00	✓
----------	---------	---

Reset and diagnose control unit and fault code

\$ >50.00	380.00	✓
-----------	--------	---

Remove and reinstall front RH door inner components to assist repair

\$ 80.00	150.00	✓
----------	--------	---

Lump sum repair
Repair days 8

2,240.00

Grand Total: \$ 33,984.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Survey	Resurvey
28/10/2021	29/10/2021
1545 hrs	1530 hrs
T. Lim	T. Lim
AW	AW

Parts	16,689.06
SN	860.00
Labour	2,240.00

19,789.06
@ 20% 3,957.81

LS 15,800/2 T. Lim
AW 7/11/2021

15,831.25