



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2201371

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 14/03/2022
Reference CC6/CTI21011024/Epa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SJC 5125G
Insured Veh. SLU 7201M
Claim No. SNM21D206161/C02
Policy No. DMPCSNW00058252100
Accident Date 27/10/2021
Inspection Date 29/10/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21011024/Epa3q2	
			Date: 14/03/2022	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLU 7201M	Veh. Inspected	SJC 5125G	
Policy No.	DMPCSNW00058252100	Coverage (\$)	0.00	
Claim No.	SNM21D206161/C02	Excess (\$)	0.00	
Assign From		Assign Date	29/10/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA STREAM	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	RN61053748	Colour	GREY	
Odometer	24003 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R17	PIRELLI	5 mm	
L/H Front Tyre	225/40 R17	PIRELLI	5 mm	
R/H Rear Tyre	225/40 R17	PIRELLI	5 mm	
L/H Rear Tyre	225/40 R17	PIRELLI	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/10/2021	Inspection Date	29/10/2021	
Survey held at	AUTOMOTIVE REPAIR CENTRE PTE LTD 38 WOODLANDS INDUSTRIAL PARK E1 # 05-18 SINGAPORE 757700			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJC 5125G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DENTED	720.00	655.00
10	FRONT BUMPER CLIPS @\$5.00	NECESSARY	50.00	30.00
1	FRONT BUMPER RETAINER RH	BROKEN	30.00	30.00
1	FRONT BUMPER RETAINER LH	BROKEN	30.00	30.00
1	FRONT HEAD LAMP LH	BROKEN	780.00	780.00
1	FRONT HEAD LAMP BRACKET LH	BROKEN	50.00	50.00
1	FRONT FENDER LH	DENTED	500.00	500.00
1	FRONT FENDER SHIELD LH	TORN	80.00	80.00
10	FRONT FENDER CLIP @\$5.00	NECESSARY	50.00	20.00
	LESS 20% DISCOUNT		-	-435.00
			2,290.00	1,740.00
<u>LABOUR</u>				
	SPRAY PAINTING FRONT BUMPER AND FRONT FENDER LH .		500.00	400.00
	REPAIR AND REPLACE AFFECTED ACCIDENT PARTS.		500.00	400.00
	CHECK AND RECTIFY ELECTRICAL WIRING.		30.00	30.00
			1,030.00	830.00
GRAND TOTAL			3,320.00	2,570.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,050.00

Report Ref No. CC6/CTI21011024/Epa3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJC 5125G

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJC 5125G

RE-INSPECTION

