

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2110-225

DATE : 27-Oct-2021

POLICY NO. : BUDGETDIRECT

VEHICLE REG. NO. : SJC5125G

VEHICLE MAKE : HONDA STREAM 1.8 A

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
 3 Anson Road, #15-00 Springleaf Tower
 Singapore 079909
 Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Front Bumper	1	\$ 720.00	\$ 720.00
2	Front Bumper Clips	10	\$ 5.00	\$ 50.00
3	Front Bumper Retainer RH	1	\$ 30.00	\$ 30.00
4	Front Bumper Retainer LH	1	\$ 30.00	\$ 30.00
5	Front Head Lamp LH	1	\$ 780.00	\$ 780.00
6	Front Head Lamp Bracket LH	1	\$ 50.00	\$ 50.00
7	Front Fender LH	1	\$ 500.00	\$ 500.00
8	Front Fender Shield LH	1	\$ 80.00	\$ 80.00
9	Front Fender Clip	10	\$ 5.00	\$ 50.00
Total Spare Parts				\$ 2,290.00
	<u>LABOUR</u>			
10	Spray painting Front Bumper and Front Fender LH	1	\$ 500.00	\$ 500.00
11	Repair and Replace Affected Accident Parts	1	\$ 500.00	\$ 500.00
12	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 1,030.00
Amount Before Excess				\$ 3,320.00
Add GST @ 7%				232.40
Total Amount Payable				\$ 3,552.40

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.