



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0886/2021/KS
DATE : 29-Oct-21
WIP : 50966

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY

YOUR INSURED VEH NO : SLN 6712 Z

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

3 days - ok - Johnny Boo

8-Dec-21

OWNER'S NAME : MR SONG KIM SENG
ADDRESS : BLK 289B BUKIT BATOK ST 25
#05-204
SINGAPORE 651289
TELEPHONE : HP +65 98239295
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO :
VEHICLE NO : **SJN 8600 Z**
MODEL CODE : AUDI Q5 2.0 TFSI
MODEL YEAR : 14/12/2018
ENGINE NO : DAX 0467627
CHASSIS NO : WAUZZZF5J2247760
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 27-Oct-21
PLACE OF ACCIDENT : 2 MATTAR RD, SG 387724

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLN 6712 Z

| S/N | NATURE OF JOBS | | ESTIMATED CHARGES | SURVEYOR'S RECOMMENDATIONS |
|-----------------------------|---|----------|------------------------------|---------------------------------------|
| 1 | TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION. | S/N \$ | 280.00 \$ | 280.00 |
| 2 | TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$ | 1,050.00 \$ | 500.00 |
| 3 | TO RESPRAY REAR BUMPER. | \$ | 900.00 \$ | 550.00 |
| 4 | TO CARRY OUT DIAGNOSTIC CHECK. | S/N \$ | 192.00 \$ | 192.00 |
| TOTAL LABOUR CHARGES | | : | \$ 2,422.00 \$ | 1,522.00 |

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 6712 Z

| | | | DAMAGED PARTS & PRICES | |
|-----------------------------|---------------------------------------|-----|-----------------------------------|--------------------|
| S/N | PARTS DESCRIPTION | QTY | S/NETT | REMARKS |
| 1 | REAR BUMPER | 1 | \$ 2,070.00 | \$ 1,656.00 |
| 2 | REAR BUMPER FIXING PARTS | 1 | \$ 193.00 | |
| 3 | REAR BUMPER LOCKING MECHANISM LH / RH | 2 | \$ 28.00 | |
| 4 | REAR BUMPER ADAPTOR - LH / RH | 2 | \$ 76.00 | |
| 5 | REAR BUMPER SPOILER | 1 | \$ 237.00 | \$ 189.60 |
| 6 | REAR LIGHT REFLECTOR - LH / RH | 2 | \$ 60.00 | |
| 7 | REAR BUMPER REINFORCEMENT BEAM | 1 | \$ 603.00 | |
| 8 | REAR BUMPER BRACKET - LH / RH | 2 | \$ 58.00 | |
| 9 | REAR PARKING AID SENSOR INNER / OUTER | 2 | TBC | |
| 10 | REAR PARKING AID SENSOR SEAL RING | 4 | \$ 14.00 | |
| 11 | SUNDRIES | | \$ 250.00 | |
| TOTAL SPARE PARTS | | | \$ 3,589.00 | \$ 1,845.60 |
| TOTAL LABOUR CHARGES | | | \$ 2,422.00 | \$ 1,522.00 |
| GRAND TOTAL | | | \$ 6,011.00 | \$ 3,367.60 |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bi-81/12/21



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT