



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #02-29

Singapore 417807

Tel: 6702 4282 Fax: 6702 4202

NZT2603032480

TRA 16.

Xiao Tong.

Page No. 1 Oct 21

Vehicle No. EZ68J TOYOTA ALLION

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR ADJUSTMENT
PARTS (LIST ITEMS)				
1	REAR BOOTLID <i>Not m</i>		977.50	✓
1	REAR BOOTLID LOGO <i>Not m</i>		71.00	✓
1	REAR BOOTLID CHROME <i>Not m</i>		214.00	✓
1	REAR BOOTLID WEATHERSTRIP <i>Not m</i>		154.80	✓
1	REAR BOOTLID LOCK <i>Not m</i>		320.00	✓
2	REAR BOOTLID HINGE LH & RH @\$114.50 <i>Not m</i>		229.00	✓
1	REAR BUMPER RH <i>De lnd</i>		1243.00	1080
2	REAR BUMPER SIDE RETAINER LH & RH @\$101.00 <i>LH Dngd</i>		202.00	58
2	REAR BUMPER REFLECTOR LH & RH @\$95.00 <i>LH Crnd</i>		180.00	95
2	REAR BUMPER BRACKET LH & RH @\$85.00 <i>LH Dnted</i>		170.00	85
1	REAR END PANEL <i>Dented</i>		598.00	✓
1	REAR END PANEL TOP GARNISH <i>De lnd</i>		197.00	✓
2	REAR TAILLAMP LH & RH @\$347.30 <i>Lt Crnd</i>		694.60	347.30
2	REAR TAILLAMP BRACKET LH & RH @\$53.00 <i>Not m</i>		106.00	✓
<i>Antenna Sensor 155 ✓</i>			5356.90	
<i>Crnd</i>			1339.23	25%
less			4017.68	
SPECIAL NETT ITEMS				
1 SET	REAR BUMPER CLIPS <i>Not m</i>		100.00	30
1 SET	REAR CAR PLATE WITH COVER <i>Not m</i>		70.00	✓
1 SET	REVERSE SENSOR <i>Dngd</i>		280.00	280
1	REAR END PANEL SEALANT <i>Not m</i>		100.00	60
Total Parts			4567.68	

2841.10

2130.82

290



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-23

Singapore 417807

Tel: 6702 4282 Fax: 6702 4202

Page No. 2

Vehicle No. EZ68J TOYOTA ALLION

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
1	<u>LABOUR</u> To remove the affected parts & fittings to commence repairs and replace damaged parts	1600.00 600	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1400.00 600	
3	To remove and refix wiring at damaged areas	120.00 30	
4	To perform anti rust treatment on affected areas	200.00 60	
5	To conduct water seepage test	120.00 X	1350
6	To remove and refix cushion and inner trim	150.00 60	
7	To remove rear boot mechanism	120.00 X	
Labour Total :		3710.00	
TOTAL (PARTS & LABOUR):		7727.68	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lim
H.S.

28/10/21

05 Days

Total: 3770.82

C/S: 3K ✓

3K