

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

## ESTIMATE OF REPAIR

Veh# : GBL3303U

Accident Date : 26/10/2021

Location : WESTCOAST HIGHWAY SLIP ROAD ENTERING JALAN BUROH (PIONEER ROAD)

Model: NISSAN NV200

11/5/2021

3P: XD2787U (FIRST CAP)

VM20

S/Nos	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper <i>Repld</i>			695.90
2	1 pc	Rear bumper o/s retainer <i>NEU</i>			86.60
3	10 pcs	Rear bumper clips <i>NEU</i>		30.00	
4	1 pc	Rear o/s tail lamp panel <i>Distld</i>			
5	1 pc	Rear o/s tail lamp <i>Repld</i>			364.60
6	1 pc	Rear o/s tail lamp inner seal <i>NEU</i>			20.00
7	1 pc	Rear tail gate <i>Distld</i>			1,764.60
8	1 pc	Rear tail gate weatherstrip <i>NEU</i>			52.50
9	1 pc	Rear o/s tail gate shock absorber <i>Missing</i>			310.60
10	1 pc	Rear o/s tail gate shock absorber bracket <i>NEU</i>			76.50
11	1 pc	Rear o/s stopper <i>NEU</i>		65.40	
12	1 pc	Rear tail gate 6 PAX emblem		15.00	
13	1 pc	Rear tail gate 70 KMPH emblem		15.00	
14	1 pc	Rear tail gate emblem		110.40	
15	1 pc	Rear tail gate nv200 emblem		86.50	
16	1 pc	Rear tail gate VANETTE emblem		75.40	
17	1 pc	Rear tail gate sticker		150.00	
18	1 pc	Rear tail gate windscreen moulding <i>NEU</i>		80.00	
19	1 pc	Rear tail gate sealant <i>NEU</i>		60.00	
20	1 pc	Rear tail gate lock <i>NEU</i>			245.50
21	1 pc	Rear 600kg sticker <i>NEU</i>		8.00	
22	1 pc	Rear o/s body panel <i>Distld</i>		1709	2,126.80
23	1 pc	Rear o/s body panel inner <i>Distld</i>		1637	1,760.20
24	1 pc	Rear o/s body panel glass <i>Shattered</i>			628.50
25	1 pc	Rear o/s body panel glass moulding		80.00	
26	1 pc	Rear o/s body panel glass sealant <i>NEU</i>		60.00	
27	1 pc	Rear o/s body panel glass solar film		150.00	
28	1 pc	Rear o/s body panel inner board <i>Repld</i>			160.50
29	8pcs	Rear o/s body panel inner board clips <i>NEU</i>		24.00	
30	1 pc	Rear o/s body panel sticker <i>NEU</i>		200.00	
31	1 pc	Rear o/s sliding door <i>Distld</i>		1282	1,499.50
32	1 pc	Rear o/s sliding door glass <i>Repld</i>			665.6
33	1 pc	Rear o/s sliding door glass moulding <i>NEU</i>		80.00	
34	1 pc	Rear o/s sliding door glass sealant <i>NEU</i>		60.00	
35	1 pc	Rear o/s sliding door glass solar film <i>NEU</i>		150.00	
36	1 pc	Rear o/s sliding door guide hinge (upper) <i>NEU</i>			95
37	1 pc	Rear o/s sliding door guide hinge (lower) <i>NEU</i>			95



38	1 pc	Rear o/s sliding door guide hinge (middle) <i>new</i>			110	+
39	1 pc	Rear o/s sliding door lock (rear)			201	+
40	1 pc	Rear o/s sliding door lock catch (rear)			88	+
41	1 pc	Rear o/s sliding door lock (front)			214	+
42	1 pc	Rear o/s sliding door lock catch (front)			85	+
43	1 pc	Rear roof lining <i>coupled</i>			1,325.60	-
44	1 pc	Rear roof panel <i>Reps</i>			2490	+
45	1 pc	Rear o/s sliding door guide <i>Best</i>			218.40	-
46	1 pc	Rear o/s sliding door guide garnish <i>Missing</i>			76.50	-
47	1 pc	Rear o/s sliding door guide handle <i>at</i>			233.10	-
48	1 pc	Front o/s driver door <i>Dented</i>		1287	1,741.60	✓
49	1 pc	Front o/s driver door sticker <i>SLN</i>		250.00		✓
50	1 pc	Front o/s driver door company sticker <i>SLN</i>		25.00		✓
51	1 pc	Front o/s fuel lid <i>Dented</i>			169.60	-
52	1 pc	Front o/s side mirror <i>cracked</i>			556.40	-
53	1 set	Front o/s door guard protector <i>SLN</i> <i>nn</i> <b>X</b>		<del>120.00</del>		
		<b>\$13,181.40</b> <del>13181.40</del> <i>S.N: 165130</i>	Sub Total:	0.00	1894.70	14,779.10
				30%	0%	10%
		<b>\$11,863.26</b> <del>11863.26</del>	After Less %:	<b>0.00</b>	<b>1894.70</b>	13,301.19
		<b>Labour</b>				
1		To dismantle damaged parts, straighten & welding.		2,600.00	1800	
2		To spray painting.		1,800.00	1400	
3		To remove and replace rear o/s fender glass		140.00	60	
4		To remove and replace rear o/s sliding door glass		140.00	60	
5		To remove and refit rear windscreen		150.00	120	
6		To remove and refit rear o/s sliding door <i>Settings</i>		100.00	60	
7		To remove and refit rear o/s tail gate <i>Settings</i>		100.00	80	
8		To remove and replace upholstery to facilitate repair		150.00	120	
9		To remove and refit rear reverse sensor		40.00	✓	
10		To check wiring		100.00	30	
11		To re seal anti rust.		100.00	✓	
		Sub Total:		<b>5,420.00</b>		
		<b>Total:</b>		<b>20,615.89</b>		


*Chan*

Chan San Choon  
Director  
DipEng, AAE MIMI,MSAE(Aust)

*Adrian G*  
*P/P 27/10/21.*  
*14 Days.*



**AL 8778 1999**  
24 hr accident call



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*total: 17,392.56*  
*CP/P*