



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref : WH0882				
Vehicle No. : SGQ5959D		Page No. 1		
Make & Model : HONDA SHUTTLE 1.5G CVT SENSING				
QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Tail lamp RH <i>BR</i>		521.00	
1	Boot lid lamp RH <i>BR</i>		420.00	
1	Rear bumper <i>CRV</i>		860.00	
2	Rear bumper side retainer LH/RH @2*\$26 <i>? BR</i>		52.00	<i>26</i>
1	Rear Fender (Repair refer to labor) <i>x R</i>		0.00	<i>1827 -209 1461.60</i>
Part Items Total:			1853.00	
			-20%	-370.60
			1482.40	
SPECIAL NETT ITEMS				
1	Rear bumper clips <i>APC</i>		<i>30</i> 35.00	
SN Items Total:			4852.80	<i>30</i>
Total Parts:			6335.20	



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref : WH0882
Vehicle No. : SGQ5959D
Make & Model : HONDA SHUTTLE 1.5G CVT SENSING

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	600.00	490
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	400.00 /	
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	30.00 /	
4	To perform anti-rust treatment on affected areas	30.00 /	860
Labour Total :		1060.00	
TOTAL (PARTS & LABOUR):		7395.20	

Steve (LKK)
28/10/21, 11.30am

WM PL
P/P
My B/L sy
3 days

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before repair spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-1461.60
N-30
L-860
P/P - 2351.60