

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0880/2021/ZK
DATE : 25-Oct-21
WIP : 50500

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 27/10/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

7 days esclude 1 Sunday

Johnny Boo 11 Jan 22

OWNER'S NAME : MR YAP EWE JIN BENEDICT (YE YAOJUN)
ADDRESS : 4 LORONG M TELOK KURAU
#03-04
SINGAPORE 425283
TELEPHONE : HP +65 96389069
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100400488-06
VEHICLE NO : **SKR 5186 P**
MODEL CODE : A3 SEDAN 1.4 TFSI
MODEL YEAR : 12/2/2015
ENGINE NO : CZC 218094
CHASSIS NO : WAUZZZ8V6F1057644
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 23-Oct-21
PLACE OF ACCIDENT : STILL ROAD OPPOSITE ESSO

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKR 5186 P

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY. <i>(Lock carrier replaced)</i>	S/N \$	360.00	\$ 360.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE	S/N \$	700.00	\$ 500.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND BITH HEADLIGHT.TO REPAIR BOTH FRONT FENDERS.RE- ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.	\$	2,100.00	\$ 500.00
4	TO RESPRAY FRONT BUMPER , BONNET AND BOTH FRONT FENDERS.	\$	3,500.00	\$ 1,100.00
5	SUPPLEMENTARY	\$	3,500.00	\$ 2,650.00
6	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 10,352.00	\$ 5,302.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKR 5186 P

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,233.00	\$	1,786.40
2	FRONT BUMPER FIXING PARTS	1	\$ 187.00		
3	FRONT BUMPER COVER TRIM - LH / RH	2	\$ 326.00		
4	FRONT BUMPER CLOSING ELEMENT - CENTER	1	\$ 163.00		
5	FRONT BUMPER PULL STRAP - LOWER	4	\$ 206.00		
6	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 78.00	\$	60.96
7	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 218.00	\$	87.20
8	FRONT RADIATOR GRILLE	1	\$ 691.00	\$	552.40
9	FRONT RADIATOR GRILLE COVER	1	\$ 98.00		
10	FRONT SIDE REINFORCEMENT	1	\$ 795.00	\$	636.00
11	FRONT BUMPER FOAM FILLER PIECE	1	\$ 137.00	\$	109.60
12	FRONT REINFORCEMENT COVER	1	\$ 56.00	\$	44.48
13	CAUTION STICKER	1	\$ 14.00	\$	10.88
14	AIR CINDITIONER STICKER	1	\$ 8.00	\$	5.68
15	HORN - LH / RH	2	\$ 400.00		
16	FRONT WHEEL HOSUING LINER - LH / RH	2	\$ 338.00		
17	HEADLIGHT - LH / RH	2	\$ 5,282.00	\$	4,225.60
18	HEADLIGHT LIFT CYLINDER - LH / RH	2	\$ 386.00		
19	HEADLIGHT HOSE	1	\$ 182.00		
20	FRONT RADIATOR AIR GUIDE - LH / RH	1	\$ 50.00	\$	38.88
SUB TOTAL SPARE PARTS		:	\$ 11,848.00	\$	7,558.08

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKR 5186 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		<i>\$ 7,558.08</i>
21	FRONT RADIATOR AIR GUIDE - RH OUTER	1	\$ 8.00	
22	FRONT RADIATOR AIR GUIDE - UPPER CENTER	1	\$ 12.00	<i>\$ 9.44</i>
23	FRONT NO PLATE	S/N	\$ 60.00	<i>\$ 60.00</i>
24	Added parts - see attached		\$ 904.00	<i>\$ 722.00</i>
25	SUNDRIES		\$ 300.00	
TOTAL SPARE PARTS		:	\$ 13,132.00	<i>\$ 8,349.52</i>
TOTAL LABOUR CHARGES		:	\$ 10,352.00	<i>\$ 5,302.00</i>
GRAND TOTAL		:	\$ 23,484.00	<i>\$ 13,651.52</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-28/12/21



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0880/2021/ZK 23-Nov-21 CHANG 1 of 1 SKR 5186 P AUDI A3 1.4 TFSI	
Quantity	Description	Unit Price	Amount	
<u>Labours</u>				
1	TO REMOVE AND REINSTALL AIRCON CONDENSE ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT AIR COND VACUUM AND REGAS.	S/N \$ 1,400.00		
2	TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.	\$ 2,100.00		
<u>Parts</u>				
1	FRONT LOCK CARRIER	\$ 727.00	\$	581.60
2	COOLANT	\$ 95.00	\$	75.52
3	BONNET CATCH HOOK	\$ 63.00	\$	50.32
4	OUTER TEMP. SENSOR BRAKCET	\$ 19.00	\$	14.56
			\$	722.00
	GRAND TOTAL	\$ 4,404.00		

For Premium Automobiles Pte Ltd

Authorised Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT