

Claim Audit

AUDIT TRAIL			
No.	On	Audit	Remarks
1	25 Oct 2021 16:37	Clm Veh Model Changed	
			Reg No: SKR5186P. Policy No: 2100400488-06. Acct Date: 2021/10/23. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:SPOR21AP0002
2	25 Oct 2021 16:37	Clm Created	
3	26 Oct 2021 11:50	Clm Registration Modified	Acct Time:13:40:00->13:00:00. Pol No:2100400488-06->2100400488. Init.Est.:> 5,000 - 6,000.
4	26 Oct 2021 11:52	Clm Veh Model Changed	(204858) AUDI A3 1.4 SEDAN TFSI (AMBIENTE) (A).
5	28 Oct 2021 12:51	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.
6	28 Oct 2021 12:51	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)
7	28 Oct 2021 12:51	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):
8	28 Oct 2021 12:51	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2021/11/09
9	28 Oct 2021 12:51	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.
10	28 Oct 2021 12:51	Clm Registration Modified	Rep:1137->200611.
11	28 Oct 2021 12:51	Clm Veh Model Changed	(204858) -> (205448) AUDI A3 1.4 TFSI AMBIENTE MY 15 (A).
12	28 Oct 2021 12:51	Adj Adjuster Assigned	[None] -> ADRIAN LING
13	28 Oct 2021 15:12	Adj Rpt Initiated	
14	28 Oct 2021 15:12	Clm Dtl Modified	Claim Conclusion: -> 3.
15	28 Oct 2021 15:12	Clm Dtl Modified	JPJ Reg. Date: -> 2015/02/12.
16	28 Oct 2021 15:12	Clm Details Notified	
17	29 Oct 2021 09:01	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2021/11/09
18	29 Oct 2021 09:02	Adj Mandate Request	Cur Req:20793.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.
19	29 Oct 2021 10:01	Clm Registration Modified	Excess: -> 300.00. Excess Waived: -> 300.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.
20	29 Oct 2021 15:15	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2021/11/09. Mandate Remarks: Vehicle may commence repair (Repair Limit @ \$20K) Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and
21	29 Oct 2021 15:15	Adj Mandate Set	Approved:10689.00:Vehicle may commence repair (Repair Limit @ \$20K) Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair and do

[] Merimen Administrator

[I] Merimen Administrator

[I] Low, Xianyu

[I] Low, Xianyu

[] CELINE FONG

[] CELINE FONG

[A] CELINE FONG

[A] CELINE FONG

[A] CELINE FONG

[A] CELINE FONG

[A] CELINE FONG

[A] CELINE FONG

[A] Elaine Kuan Hwa Meen

[A] Elaine Kuan Hwa Meen

[A] Elaine Kuan Hwa Meen

[A] Elaine Kuan Hwa Meen

[A] SHIAU CHAN

[A] SHIAU CHAN

[I] Hor, Yinrul

[I] Lim, Kok-Chong

[I] Lim, Kok-Chong

AUDIT TRAIL				
No.	On	Audit	Remarks	By
22	24 Nov 2021 15:58	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2021/11/09	[A] SHIAU CHAN
23	24 Nov 2021 15:59	Adj Mandate Request	Cur.Req:16286.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY APPROVE ON SUPPLEMENTARY.	[A] SHIAU CHAN
24	24 Nov 2021 17:29	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2021/11/09. Mandate Remarks: (Repair Limit @ \$20K) Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair	[I] Lim, Kok-Chong
25	24 Nov 2021 17:29	Adj Mandate Set	Approved:15371.00:(Repair Limit @ \$20K) Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair and document into Merimen.	[I] Lim, Kok-Chong

Date From		 	Date To		 	Audit Type	None	Go
------------------	----------------------	---	----------------	----------------------	---	-------------------	-----------------------------------	-----------------------------------

ACTIVITY

No record

Merimen Billing for this case - Transaction History								
Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2736704	28 Oct 2021 15:12:19	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKR5186P		11.00