

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0880/2021/ZK

23-Nov-21

CHANG


1 of 1

SKR 5186 P

AUDI A3 1.4 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	TO REMOVE AND REINSTALL AIRCON CONDENSER ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT AIR COND VACUUM AND REGAS.	S/N \$ 1,400.00	✓
2	TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.	\$ 2,100.00	1250
Parts			
1	FRONT LOCK CARRIER	\$ 727.00	✓
2	COOLANT	\$ 95.00	✓
3	BONNET CATCH HOOK	\$ 63.00	✓
4	OUTER TEMP. SENSOR BRACKET	\$ 19.00	✓
GRAND TOTAL		\$ 4,404.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian Ling
23/11/21
SLS

Carin

23/11/21

Botak/

wip: 50500.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

 1-16-Admiral 
 - 4 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKR 5186 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER Dehd	1 S	2,233.00	✓
2	FRONT BUMPER FIXING PARTS New	1 S	187.00	+
3	FRONT BUMPER COVER TRIM - LH / RH New	2 S	326.00	+
4	FRONT BUMPER CLOSING ELEMENT - CENTER New	1 S	163.00	+
5	FRONT BUMPER PULL STRAP - LOWER New	4 S	206.00	+
6	FRONT BUMPER GUIDE SECTION (LH) (RH) New could	2 S	78.00	+
7	FRONT BUMPER AIR GUIDE GRILLE - LH / RH RH ?, LH MISSING	2 S	218.00	109
8	FRONT RADIATOR GRILLE Cracked	1 S	691.00	✓
9	FRONT RADIATOR GRILLE COVER ?	1 S	98.00	?
10	FRONT SIDE REINFORCEMENT Dented	1 S	795.00	✓
11	FRONT BUMPER FOAM FILLER PIECE Could	1 S	137.00	✓
12	FRONT REINFORCEMENT COVER Could	1 S	56.00	✓
13	CAUTION STICKER Free	1 S	14.00	✓
14	AIR CINDITIONER STICKER	1 S	8.00	✓
15	HORN - LH / RH ?	2 S	400.00	?
16	FRONT WHEEL HOSUING LINER - LH / RH New	2 S	338.00	+
17	HEADLIGHT - LH / RH Cracked	2 S	5,282.00	✓
18	HEADLIGHT LIFT CYLINDER - LH / RH New	2 S	386.00	+
19	HEADLIGHT HOSE New	1 S	182.00	+
20	FRONT RADIATOR AIR GUIDE - (LH) (RH) Dehd	1 S	50.00	✓
SUB TOTAL SPARE PARTS			\$	11,848.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

photo

PREMIUM AUTOMOBILES



35 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 7323 FAX: 6841 1183
EMAIL: NURA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKR 5186 P

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	FRONT RADIATOR AIR GUIDE - RH OUTER	1	\$ 8.00		
22	FRONT RADIATOR AIR GUIDE - UPPER CENTER <i>rhhd</i>	1	\$ 12.00		
23	FRONT NO PLATE <i>Dented</i>	S/N	\$ 60.00		
24	SUNDRIES		\$ 300.00		
TOTAL SPARE PARTS		:	\$ 12,228.00		
TOTAL LABOUR CHARGES		:	\$ 6,852.00		
GRAND TOTAL		:	\$ 19,080.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.