

Section A - Accident Details

Registration Number	SG5871H
Case Reference Number	BUS/10/21/5034
Registration Date	11/16/2017
Company Type	SMRT Buses Ltd
Make	MAN
Model	A95
Name of Driver	Jayaraj A/L Govindan
Type of Accident	Head To Side
Accident Date and Time	10/9/2021 7:50 PM
Accident Reported Date and Time	10/9/2021 9:45 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG5871H-REAR DOOR WINDOW GLASS PANEL SHATTERED AND BODY DENTED. PRIVATE CAR (TP) INSURED WITH
Prepared Date and Time	10/25/2021 11:35 AM
Chassis Number	WMAA95ZZXG7003551
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,650.00	\$0.00
Total Spray Cost	\$432.00	\$0.00
Total Spare Part Cost	\$12,428.80	\$0.00
Total Other Cost	\$500.00	\$0.00
TOTAL COST	\$16,010.80	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	4 days
Prepared / Adjusted By	Jeong Choon Hwee	
ARC / Surveyor Sign Off Date	26/10/2021 10:51 AM	
Signature		☒
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757706
FAX Number : 63665592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 27/10/2021
User ID : JeongCH

Section D - Details of Repair Estimates

Part 1 - Labour Works		Adjusted by Surveyor, if applicable							
Job Scope	Quotation from AR		1590						
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	\$2,650.00								
Total Labour	\$2,650.00								
Part 2 - Spray Painting & Panel Beating Related Works		Adjusted by Surveyor, if applicable							
Job Scope	Quotation from ARC		262						
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$432.00								
Total Spray Painting & Panel Beating	\$432.00								
Part 3 - Other Costs - Accident and Accident Repair Related Expense		Adjusted by Surveyor, if applicable							
Job Scope	Quotation from ARC		500 receipt? X11						
TOWING CHARGE	\$500.00								
Total Other Costs	\$500.00								
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6013487	BODY LH	124-2-2-001-009	SIDE PANEL L9	1.00	\$580.00	10.00	\$522.00	Replace	by X repair
		G20.07.07.02	PARTITION EXIT NS	1.00	\$825.00	10.00	\$562.50	Replace	ca
		PEA21430	ALUMINIUM PROFILE	1.00	\$525.00	10.00	\$472.50	Replace	st
		Q18MY1B3	REAR DOOR (DOOR NO4)	1.00	\$14,750.00	10.00	\$13,275.00	Replace	Lo
4006314	CONSUMABLE		ADHESIVE DIRECT GLAZING	4.00	\$37.00	0.00	\$148.00	Replace	ne
4006315	CONSUMABLE		ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	ne
6010568	DOOR		FRAME EXIT DOOR FOR MAN A22 BUS	1.00	\$440.00	10.00	\$396.00	Replace	cut
4006313	CONSUMABLE	SIKA8 Primer-206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	ne
Total					\$17,117.00		\$15,536.00		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1852
15014
16866
20%
13492.80
H/S - \$13,500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ASUL
Hp 90010068
4 days
Hs
27/10/21 @ 1145
Resurvey after repair