

3rd party claim (LKK)
 Surveyor: Adrian Ling (LKK)

LKK Auto Consultants hence notify **MAX MOTORS** SING:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

1 Kaki Bukit Ave 6, #01-98, Autobay @ Kaki Bukit Bldg E, Singapore 417883
 Tel: 87519676 | Email: Linwei@maxmotors.com.sg

Acknowledged by Repairer

Signature:

ATTN: MOTOR CLAIMS DEPARTMENT

TP China

Dense: KM1H0U41BR 94703436

ESTIMATION QUOTE

VEHICLE NO : SJN9663K
 MAKE MODEL : HYUNDAI/AVANTE
 REFERENCE : 1044
 DOA : 26 October 2021
 CLAIM TYPE : Third party claim

Page 1 of 2

LIST ITEMS	QTY	LIST PRICE (\$)	REMARKS
REAR DOOR PANEL RH LH Distorted	1	\$ 1,289.00	114
REAR DOOR TOP MOULING RH LH	1	\$ 118.00	X
REAR DOOR HINGE UPPER RH LH	1	\$ 76.00	+
REAR DOOR HINGE LOWER RH LH	1	\$ 75.00	+
REAR DOOR CHECKER RH LH	1	\$ 89.00	X
REAR DOOR INNER TRIM RH LH cruked	1	\$ 485.00	✓
REAR DOOR LOCK ASSY	1	\$ 584.00	291
REAR DOOR REGULATOR AND MOTOR RH LH Dmd	1	\$ 533.00	385
REAR FENDER RH LH Distorted	1	\$ 1,233.00	✓
REAR FENDER INNER SHIELD RH LH torn	1	\$ 154.00	✓
REAR WINDSCREEN MOULDING	1	\$ 180.00	✓
REAR BUMPER	1	\$ 674.00	X
REAR BUMPER RETAINER LH RH	1	\$ 65.00	X
REAR BUMPER RETAINER RH LH	1	\$ 65.00	✓
REAR TAIL LAMP RH LH	1	\$ 343.00	X
REAR KNUCKLE ARM RH LH Dmd	1	\$ 424.00	✓
REAR KNUCKLE ARM BEARING RH LH Dmd	1	\$ 159.00	✓
REAR LOWER ARM RH LH Bent	1	\$ 384.00	✓
REAR SHOCK ABSORBER RH LH Bent	1	\$ 394.00	✓

Rocker Panel LH. Dmd

\$ 7,324.00
 LESS 20 % \$ 1,464.80
 SUBTOTAL \$ 5,859.20

BALANCE C/F \$ 5,859.20

SPECIAL NETT ITEMS	QTY	LIST PRICE (\$)	REMARKS
BALANCE B/F		\$ 5,859.20	

RIM LH	1	\$ 650.00	400
TYRE Punctured	1	\$ 250.00	180
REAR DOOR INNER TRIM CLIP	1 SET	\$ 40.00	30
REAR FENDER INNER SHIELD CLIP	1 SET	\$ 30.00	✓
REAR BUMPER CLIP	1 SET	\$ 30.00	✓
JOINT SERALANT	1	\$ 120.00	60
WINDSCREEN SEALANT	1	\$ 120.00	60
SUBTOTAL		\$ 1,240.00	

BALANCE C/F \$ 7,099.20

LABOUR	QTY	LIST PRICE (\$)	REMARKS
BALANCE B/F		\$ 7,099.20	

CHECK REAR LIGHTNING AND WIRING SYSTEM		\$ 100.00	30
REMOVE, REFIT REAR LINING, TIRM AND GANRISH		\$ 150.00	80
REMOVE AND REFIT FUEL TANK		\$ 150.00	80
REMOVE, REFIT REAR REVERSE SENSOR		\$ 120.00	X
REMOVE AND REFIT REAR WINDSCREEN		\$ 120.00	✓
TRANSFER PARTS, ATTACHMMENT FROM OLD DOOR TO NEW		\$ 200.00	80
PANEL BEATING ON AFFECTED AREAS AND RENEW PARTS		\$ 1,400.00	1,000
SPRAY PAINTING ON AFFECTED AREAS		\$ 1,200.00	800
APPLY ANTI RUST ON AFFECTED AREAS		\$ 100.00	✓
SUBTOTAL		\$ 3,540.00	

Remove rear undercarriage
 Perform wheel alignment

350 220
 80
 Supplementary: 834.40
 Total: 8866.40
 L/S: 7.71C

GRAND TOTAL \$ 10,639.20

Adrian Ling
 96893735 h/s 28/10/21
 07 Days

MAX MOTORS

1 Kaki Bukit Ave 6 ,#01-98. Autobay @ Kaki Bukit Blk E .Singapore 417883
Tel : 87519676 | Email : Gavin@maxmotors.com.sg / Linwei@maxmotors.com.sg

ESTIMATION QUOTE

VEHICLE NO : SJN9663K
MAKE MODEL : HYUNDAI/AVANTE
REFERENCE : 1044
DOA : 26 October 2021
CLAIM TYPE : SUPPELNTARY CLAIM

ATTN : MOTOR CLAIMS DEPARTMENT

Page 1 of 2

LIST ITEMS	QTY	LIST PRICE (\$)	REMARKS
REAR LH TRAILING ARM	1	\$ 344.00	✓
REAR LH UPPER TRAILING ARM	1	\$ 378.00	✓
REAR LH STAY ARM	1	\$ 321.00	✓

\$ 1,043.00
LESS 20 % \$ 208.60
SUBTOTAL \$ 834.40
GRAND TOTAL \$ 834.40

Adrian Lin
H/S.

12358.60