



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21011043/Aqf3n2	
			Date: 17/03/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLR 3268M	Veh. Inspected	SKN 1276K
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2103214/THE	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	28/10/2021
2. Vehicle Particulars & Condition				
	Make & Model	HONDA INSIGHT	c.c	1339
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	JHMZE2850ES200086	Colour	WHITE
	Odometer	109473 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R16	BRIDGESTONE	6 mm
	L/H Front Tyre	195/65 R16	BRIDGESTONE	6 mm
	R/H Rear Tyre	195/65 R16	BRIDGESTONE	6 mm
	L/H Rear Tyre	195/65 R16	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/10/2021	Inspection Date	29/10/2021
	Survey held at	XIN HUA WORKSHOP PTE LTD 23 KAKI BUKIT AVENUE 4 #04-01 (SOUTH WING) SINGAPORE 415933		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	