



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2207786

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 19/12/2022
Reference CC6/CTI21011047/Dpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHC 7506B
Insured Veh. PA 3373J
Claim No. SNM21D206176/C02
Policy No. DMB1SNW00003562103
Accident Date 28/10/2021
Inspection Date 29/10/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21011047/Dpa3q2 Date: 19/12/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	PA 3373J	Veh. Inspected	SHC 7506B
	Policy No.	DMB1SNW00003562103	Coverage (\$)	0.00
	Claim No.	SNM21D206176/C02	Excess (\$)	0.00
	Assign From		Assign Date	29/10/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JTDKB3FU003078064	Colour	YELLOW
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	WEST LAKE	5 mm
	L/H Front Tyre	195/65 R15	WEST LAKE	5 mm
	R/H Rear Tyre	195/65 R15	WEST LAKE	5 mm
	L/H Rear Tyre	195/65 R15	WEST LAKE	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	28/10/2021	Inspection Date	29/10/2021
	Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 7

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7506B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	TO REPAIR SEE LABOUR	458.60	-
1	REAR BUMPER SIDE RETAINER	NOT NECESSARY	112.70	-
1	REAR BUMPER CLIPS	NOT NECESSARY	22.00	-
1	REAR BUMPER SIDE CLIP	NO SUCH PARTS	25.00	-
1	REAR FENDER LH	DENTED	836.70	836.70
1	REAR FENDER SHIELD (LH)	NOT NECESSARY	174.20	-
1	REAR FENDER AIR DUCT	NOT NECESSARY	165.10	-
1	PANEL SUB-ASSY ,REAR DOOR ,LH	DENTED	1,258.30	1,258.30
1	REAR DOOR HINGE UPPER	NOT NECESSARY	82.30	-
1	REAR DOOR HINGE LOWER	NOT NECESSARY	82.30	-
1	REAR DOOR CHECK	NOT NECESSARY	153.00	-
1	REAR DOOR TRIMBOARD	NOT NECESSARY	725.00	-
1	REAR DOOR INNER LOCK	NOT NECESSARY	644.70	-
1	MOTOR ,POWER WINDOW REGULATOR FRT ,LH	NOT NECESSARY	941.80	-
1	REGULATOR ,FRONT DOOR WINDOW REAR ,LH	NOT NECESSARY	228.40	-
1	REAR DOOR OUTER HANDLE	NOT NECESSARY	93.00	-
1	REAR DOOR RUBBER SEAL OUTER	SERVICEABLE	257.90	-
1	GLASS ,SUB-ASSY ,REAR DOOR ,LH	NOT NECESSARY	780.50	-
1	DOOR CENTRE PILLAR OUT(LH)	TO REPAIR SEE LABOUR	1,590.60	-
1	PANEL SUB-ASSY ,FRONT DOOR ,LH	BUCKLED	1,264.00	1,264.00
1	FRONT DOOR OUTER HANDLE (LH)	CUT	378.90	378.90
1	FRONT DOOR INNER LOCK	DAMAGED	688.80	453.80
1	FRONT DOOR HINGE UPPER	BENT	91.20	91.20
1	FRONT DOOR HINGE LOWER	BENT	91.20	91.20
1	FRONT DOOR CHECK	BENT	153.52	153.52
1	FRONT DOOR TRIMBOARD	NOT NECESSARY	725.00	-
1	FRONT DOOR WEATHERSTRIP	SERVICEABLE	457.90	-
1	FRONT DOOR RUBBER SEAL	NO SUCH PARTS	257.00	-
1	MOTOR ASSY ,POWER WINDOW FRT ,LH	NOT NECESSARY	941.80	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REGULATOR FRONT DOOR WINDOW FRT ,LH	NOT NECESSARY	228.40	-
1	MIRROR ASSY ,OUTER REAR VIEW ,LH	BROKEN	1,728.70	1,390.10
1	N/S ROCKER PANEL OUTER GARNISH	BENT / MTG BROKEN	576.00	576.00
1	REAR TYRE RIM (LH)	CUT	1,555.00	1,555.00
1	REAR WHEEL CAP (LH)	NOT FITTED	177.70	-
1	LH REAR WHEEL BEARING & HUB ASSY	DAMAGED	610.20	493.10
1	REAR CROSS MEMBER	NOT NECESSARY	2,200.40	-
1	LH REAR SHOCK ABSORBER	DISTORTED	118.30	118.30
1	LH REAR SHOCK ABSORBER MOUNTING	NOT NECESSARY	125.30	-
1	LH REAR LOWER ARM	DISTORTED	497.50	497.50
1	LH REAR UPPER ARM	DISTORTED	356.80	356.80
1	LH REAR KNUCKLE ARM	DISTORTED	810.60	405.30
1	REAR STABILIZER BAR	NOT NECESSARY	311.50	-
1	REAR STABILIZER LINK	NOT NECESSARY	151.60	-
1	LH REAR TRAILING ARM	DISTORTED	314.20	314.20
1	LH REAR ASSIST ARM	DISTORTED	342.20	342.20
1	RADIATOR GRILLE	MTG BROKEN	438.00	438.00
1	RADIATOR GRILLE EMBLEM	SERVICEABLE	88.00	-
1	FRONT BUMPER COVER	TORN	499.90	499.90
1	FRONT BUMPER REINFORCEMENT	BENT	696.40	696.40
1	FRONT BUMPER REINFORCEMENT ABSORBER (O/S)	BENT	115.70	115.70
1	FRONT BUMPER LOWER REINFORCEMENT	BENT	364.20	364.20
2	FRT BUMPER LOWER REINFORCEMENT BRACKET LH/RH @\$330.00	N/S NOT NECESSARY / O/S BENT	660.00	330.00
1	ABSORBER ,FRONT BUMPER ,LOWER	MTG BROKEN	127.70	127.70
2	FRONT SIDE MIRROR REINFORCEMENT PANEL (LH/RH) @\$320.70	NOT NECESSARY	641.40	-
2	FRONT SIDE MEMBER SIDE COVER @\$172.50	N/S NOT NECESSARY / O/S TORN	345.00	172.50
1	FRONT BUMPER SPONGE	TORN	78.80	78.80
1	FRONT BUMPER LOWER GRILLE	MTG CRACKED	166.90	166.90
1	LAMP ASSY ,FOG , RH	BROKEN	920.00	920.00

Report Ref No. CC6/CTI21011047/Dpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER SIDE RETAINER	O/S DISLODGE / N/S NOT NECESSARY	154.00	77.00
1	FRONT LOWER PANEL	BENT	320.65	320.65
2	FRONT LOWER SIDE RAIL (LH/RH) @\$230.80	N/S NOT NECESSARY / O/S BENT	461.60	230.80
1	FRONT LOWER CROSSMEMBER	NOT NECESSARY	357.70	-
1	FRONT UNDER COVER	TORN	180.80	180.80
1	FRONT UNDER COVER (RR)	TORN	457.40	457.40
1	FRONT UNDER COVER CENTER	NOT NECESSARY	523.40	-
1	FRONT BUMPER TOP GARNISH	NOT NECESSARY	225.40	-
1	COVER ,FRONT BUMPER ,HOLE, RH	DISLODGE	28.38	28.38
1	UNIT ASSY ,HEADLAMP ,RH (LED)	BROKEN	3,455.00	2,637.60
1	HEAD LAMP PANEL (RH)	BENT	240.10	240.10
1	TOP PANEL CENTRE	NOT NECESSARY	364.98	-
2	TOP PANEL SIDE @\$145.90	NOT NECESSARY	291.80	-
1	RADIATOR ASSY	BENT / MTG BROKEN	1,841.80	1,841.80
1	RADIATOR FAN GRILLE	NOT NECESSARY	632.40	-
1	GUIDE RADIATOR AIR NO.3	NOT NECESSARY	299.70	-
1	DEFLECTOR ,RADIATOR SIDE ,RH	SERVICEABLE	83.50	-
1	DEFLECTOR ,RADIATOR SIDE ,LH	SERVICEABLE	83.50	-
1	STAY ,RADIATOR SUPPORT ,RH	NOT NECESSARY	65.70	-
1	RADIATOR FAN BLADE (RH)	NOT NECESSARY	233.10	-
1	RADIATOR FAN MOTOR (RH)	NOT NECESSARY	543.70	-
1	RADIATOR FAN COWLING (RH)	NOT NECESSARY	451.30	-
1	CONDENSER ASSY ,W/RECEIVER	BENT / CRACKED	1,336.60	1,336.60
1	FENDER SUB-ASSY ,FRONT RH	TO REPAIR SEE LABOUR	945.30	-
1	FENDER SUB-ASSY ,FRONT LH	BUCKLED	945.30	945.30
1	FRONT HOUSING ASSY LH	NOT NECESSARY	958.30	-
2	FRONT FENDER SHIELD @\$38.00	TORN / DEFORMED	76.00	76.00
2	FRONT FENDER SHIELD CLIP @\$14.90	NECESSARY	29.80	29.80
2	FRONT FENDER HYBRID EMBLEM LH/RH @\$86.50	NECESSARY	173.00	173.00

Report Ref No. CC6/CTI21011047/Dpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BRACKET ,FRONT SIDE PANEL ,RH	NOT NECESSARY	86.30	-
1	BRACKET ,FRONT SIDE PANEL ,LH	NOT NECESSARY	86.30	-
1	EXTENSION ,FRONT FENDER LH	NOT NECESSARY	47.20	-
1	PROTECTOR ,FRONT FENDER UPPER ,LH	NO SUCH PARTS	46.10	-
1	GUSSET ,FRONT FENDER APRON ,LOWER LH	NOT NECESSARY	34.90	-
1	MEMBER FRONT APRON TO COWL SIDE ,UPPER LH	NOT NECESSARY	138.40	-
1	FRONT APRON TO COWL SIDE ,LOWER FRT LH	NOT NECESSARY	82.30	-
1	FRONT CUSHION SEAT (N/S)	TORN	1,180.00	1,180.00
1	FRONT CUSHIN SEAT CUSHION PAD (RH)	NOT NECESSARY	526.80	-
1	FRONT WINDSCREEN GLASS MOULDING	NOT NECESSARY	208.60	-
1	FRONT WINDSCREEN GLASS MOULDING LOWER	NOT NECESSARY	208.60	-
1	FRONT WINDSCREEN GLASS PILLAR	DENTED	343.10	343.10
1	FRONT WINDSCREEN SIDE GARNISH	NOT NECESSARY	186.40	-
1	WIPER SPARE TANK ASSY	BROKEN	486.70	486.70
1	WIPER TANK NECK	SERVICEABLE	89.40	-
2	FRONT WHEEL RIM @\$1570.55	N/S CUT / O/S NOT NECESSARY	3,141.10	1,555.00
2	FRONT WHEEL RIM CAP @\$189.60	NO SUCH PARTS	379.20	-
2	FRONT WHEEL HUB AND BEARING @\$763.80	DAMAGED	1,527.60	1,120.20
1	FRONT SUSPENSION LOWER ARM (RH)	BENT	637.50	637.50
1	FRONT SUSPENSION LOWER ARM (LH)	DISTORTED	637.50	637.50
1	FRONT SHOCK ABSORBER (LH)	BENT	401.80	401.80
1	FRONT SHOCK ABSORBER (RH)	DISTORTED	401.80	401.80
2	ABSORBER TOP MOUNTING @\$196.20	NOT NECESSARY	392.40	-
1	FRONT DRIVE SHAFT (LH)	NOT NECESSARY	1,764.00	-
1	RACK & PINION ASSY	DAMAGED	1,634.90	1,634.90
1	BAR STABILIZER	NOT NECESSARY	360.00	-
1	LINK ASSY ,FRONT STABILIZER ,LH	NOT NECESSARY	199.00	-
2	KNUCKLE STEERING RH @\$580.80	DISTORTED (1 PCS ONLY)	1,161.60	496.50
2	KNUCKLE STEERING LH @\$580.80	DISTORTED (1 PCS ONLY)	1,161.60	496.50
2	JOINT ASSY ,LOWER BALL ,FRONT (LH/RH) @\$199.98	DAMAGED	399.96	399.96
2	END SUB-ASSY ,TIE ROD ,RH @\$159.30	DISTORTED (1 PCS ONLY)	318.60	159.30

Report Ref No. CC6/CTI21011047/Dpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	END SUB-ASSY ,TIE ROD ,LH @\$159.30	DISTORTED (1 PCS ONLY)	318.60	159.30
2	SENSOR SPEED ,FRONT RH @\$446.50	NOT NECESSARY	893.00	-
2	SENSOR SPEED ,FRONT LH @\$446.50	NOT NECESSARY	893.00	-
1	ENGINE UNDER COVER	REPEATED	457.20	-
1	ENGINE UNDER COVER FRONT	REPEATED	288.30	-
1	ENGINE CROSS MEMBER	DAMAGED / DISTORTED	2,531.70	2,531.70
2	FRONT DOOR SAFETY BELT (LH/RH) @\$1038.00	ACTIVATED	2,076.00	1,693.60
2	REAR DOOR SAFETY BELT (LH/RH) @\$838.00	ACTIVATED	1,676.00	1,676.00
1	ROOF LINING	CRUMPLED	2,082.10	2,082.10
1	SIDE AIRBAG ,LH	ACTIVATED	1,479.00	1,479.00
1	AIR BAG ASSY ,FRONT SEAT ,LH	ACTIVATED	857.90	857.90
2	AIR BAG SENSORS @\$986.00	NOT NECESSARY	1,972.00	-
1	COMPUTER ASSY ,AIR BAG ECU	ACTIVATED	1,083.80	967.70
1	SENSOR AIR BAG	ACTIVATED	310.50	310.50
1	FRONT DOOR OUTER MOULDING (ADDITIONAL)	BENT	188.60	188.60
1	GLASS SUB-ASSY ,FRONT DOOR ,LH (ADDITIONAL)	SCRATCHED	780.50	780.50
1	UNIT ASSY ,HEADLAMP ,LH (LED) (ADDITIONAL)	MTG CRACKED	3,455.00	2,637.60
1	FRONT CUSHION SEAT COMPLETE (ADDITIONAL)	REPEATED	4,863.50	-
	LESS 20% DISCOUNT		-17,832.88	-
	LESS 25% DISCOUNT		-	-12,094.18
			71,331.51	36,282.53
	SPECIAL NETT ITEMS			
1	FRONT DOOR ADVERTISEMENT LOGO (SN)	NECESSARY	100.00	100.00
1	FRONT DOOR COMFORT LOGO (SN)	NECESSARY	75.00	75.00
1	REAR BUMPER ADVERTISEMENT (SN)	NECESSARY	120.00	80.00
1	REAR FENDER ADVERTISEMENT LOGO (LH) (SN)	NECESSARY	100.00	100.00
1	REAR DOOR COMFORT & APPS STICKER (SN)	NECESSARY	80.00	80.00
1	REAR DOOR ADVERTISEMENT LOGO (SN)	NECESSARY	100.00	100.00
1	N/S ROCKER PANEL GARNISH OUTER ADVERTISEMENT (SN)	NECESSARY	519.80	100.00
1	REAR TYRE (LH) (SN)	SERVICEABLE	216.00	-
1	COOLANT (SN)	NOT NECESSARY	45.00	-

Report Ref No. CC6/CTI21011047/Dpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT FENDER ADVERTISEMENT LOGO (LH/RH) @ \$100.00 (SN)	NECESSARY	200.00	200.00
2	FRONT TYRE (LH/RH) @\$216.00 (SN)	SERVICEABLE	432.00	-
			1,987.80	835.00
	LABOUR			
	PANEL BEATING .INCLUSIVE OF THE REPAIR OF REAR BUMPER,DOOR CENTRE PILLAR OUTER (LH) AND FENDER SUB-ASSY ,FRONT RH.		2,200.00	1,400.00
	SPRAY PAINTING CHARGE.		2,200.00	1,200.00
	WIRING CHARGE.		100.00	30.00
	TUFF KOTE.		100.00	40.00
	TOWING CHARGE.	NOT NECESSARY	80.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR .		150.00	80.00
	REMOVE/REFIX REVERSE SENSOR .	NOT NECESSARY	120.00	-
	REMOVE/REFIX UNDERCARRIAGE (RR).		400.00	150.00
	RE-SET REAR ABS SYSTEM.	NOT NECESSARY	400.00	-
	REMOVE/REFIX FUEL TANK.	NOT NECESSARY	80.00	-
	REMOVE/REFIX EXHAUST PIPE.	NOT NECESSARY	80.00	-
	TRANSFER OF DOOR MECHANISM FRONT .		80.00	60.00
	RE-SET FRT POWER WINDOW SYSTEM.	NOT NECESSARY	200.00	-
	TRANSFER OF DOOR MECHANISM REAR .		80.00	60.00
	RE-SET REAR POWER WINDOW SYSTEM.	NOT NECESSARY	200.00	-
	FOUR WHEEL ALIGNMENT.		120.00	60.00
	REMOVE/REFIX UNDERCARRIAGE (FRT).		800.00	150.00
	RE-SET FRT ABS SYSTEM.	NOT NECESSARY	200.00	-
	REMOVE/REFIX RADIATOR .		90.00	50.00
	REMOVE/REFIX AIRCON & REFILL GAS.		130.00	80.00
	REMOVE/REFIX FUSE BOX.	NOT NECESSARY	120.00	-
	REMOVE/REFIX FRONT WINDSCREEN GLASS .	NOT NECESSARY	120.00	-
	REMOVE/REFIX ENGINE.	NOT NECESSARY	600.00	-
	REMOVE/REFIX AIR BAG/STEERING WHEEL /DASHBOARD /SEAT.		550.00	250.00

Report Ref No. CC6/CTI21011047/Dpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:7 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.		550.00	180.00
			9,750.00	3,790.00
GRAND TOTAL			83,069.31	40,907.53
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				30,000.00

Report Ref No. CC6/CTI21011047/Dpa3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 7506B

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 7506B

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 7506B

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

