



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 ATTN: JOANNE YONG			Ref: CS3/AIG20009486/R1qf3e2-1 Date: 16/11/2021 Code: AIG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBD 1561X	Veh. Inspected	SLK 5282U	
Policy No.	2100379165	Coverage (\$)	0.00	
Claim No.	0253426446SG	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	28/10/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA ODYSSEY	c.c	2356	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JHMRC1880GC206718	Colour	GOLD	
Odometer	109691 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	GITI	6 mm	
L/H Front Tyre	215/55 R17	GITI	6 mm	
R/H Rear Tyre	215/55 R17	GITI	6 mm	
L/H Rear Tyre	215/55 R17	GITI	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	02/09/2020	Inspection Date	07/09/2020	
Survey held at	SINCERELEAD GARAGE PTE LTD 2 BUROH CRESCENT, #02-09 ACE @ BUROH SINGAPORE 627546			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	