

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21011049/AGQF3N2**Date:** 29/03/2022**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29148151AT2
Claimant Vehicle No :	SDK8811T	Insured Vehicle No :	SLV6530P
Date of Loss:	26/10/2021	Nature of Claim:	TP
		Claim No:	638610

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDK8811T		
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Engine No:	CZD221231
Reg. Date:	26/01/2016 (Man. Year: 2015)	Chassis No:	WAUZZZ8U4GR053215
Colour:	Black	Odometer:	80074 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55R17	Rear Tyre Size:	235/55R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,783.00	3,141.50	2,641.50	45.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,672.00	3,472.00	1,200.00	25.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,455.00	6,613.50	3,841.50	36.74
+ GST 7.00/7.00% (S\$)	731.85	462.95	268.90	36.74
Nett Amount (S\$)	11,186.85	7,076.45	4,110.40	36.74

INSPECTION

Date of Assignment:	28/10/2021		Premium Automobiles Pte Ltd (UBI)
Date Inspected:	29/10/2021	Inspected At:	55 Ubi Road 1
			Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Mar 2022)
Parts:	M1-SUV	AUDI Q3 1.4 TFSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDK8811T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,580.00 FS	*- FS
2	1		*REAR BUMPER FIXINF SET	Not Necessary	124.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Deformed	880.00 FS	*880.00 FS
4	1		*REAR BUMPER DIFFUSER-LH	Deformed	706.00 FS	*705.50 FS
5	1		*REAR TAIL LIGHT-LH	Cracked	457.00 FS	*457.00 FS
6	6		*HEX BOLT	Not Necessary	30.00 FS	*- FS
7	2		*REAR BUMPER PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
8	4		*REAR BUMPER PARKING AID SENSOR SEAL	Not Necessary	6.00 FS	*- FS
9	2		*REAR BUMPER WHEEL ARCH COVER-LH/RH	Necessary	1,056.00 FS	*1,055.00 FS
10	1		*SUNDRIES	Necessary	250.00 FS	*1.40 FS
11	1		*REAR BUMPER TOWING EYE COVER-LH	Deformed	43.00 FS	*42.60 FS
12	1		*REAR BUMPER CARRIER	Not Necessary	651.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	5,783.00	3,141.50
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID.CHECK FUNCTION	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,200.00	800.00
3	TO RESPRAY REAR UPPER BUMPER,REAR LOWER SPOILER AND BOTH REAR WHEEL ARCH TRIMS	New	3,000.00	2,200.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$)			4,672.00	3,472.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >