

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0439/2021/ZK
DATE : 22-May-21
WIP : 28845

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 29/10/2021

YOUR INSURED VEH NO : SLV 6530 P

MSIG INSURANCE (SINGAPORE) PTE LTD

NO 4 SHENTON WAY

#23-01 SGX CENTRE 2

SINGAPORE 068896

Attn: Motor Claims Dept

Tel: 6827 27692 - Fax: 6225 7402

Hi Guo Qiang
3 days - ok - Johnny Boo
10-Dec-21

OWNER'S NAME : MR LIM BOON KENG
ADDRESS : 139 SERANGOON AVE 3
#16-02
SINGAPORE 556119
TELEPHONE : HP +65 9750 9390
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 5109016743-02
VEHICLE NO : **SDK 8811 T**
MODEL CODE : AUDI Q3 1.4 TFSI S
MODEL YEAR : 1/26/2016
ENGINE NO : CZD221231
CHASSIS NO : WAUZZZ8U4GR053215
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Oct-21
PLACE OF ACCIDENT : THOMSON GREEN
TRAFFIC JUNCTION TURNING RIGHT INTO HOUGANG STREET 2

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDK 8811 T

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION	S/N \$	280.00	\$ 280.00
2	TO DISMANTLE AND RENEW REAR BUMPER RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.	\$	1,200.00	\$ 800.00
3	TO RESPRAY REAR UPPER BUMPER,REAR LOWER SPOILER AND BOTH REAR WHEEL ARCH TRIMS.	\$	3,000.00	\$ 2,200.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$	4,672.00	\$ 3,472.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDK 8811 T

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER	1	\$	1,580.00	
2	REAR BUMPER FIXING SET	1	\$	124.00	
3	REAR BUMPER SPOILER	1	\$	880.00	\$ 880.00
4	REAR BUMPER DIFFUSER - LH	1	\$	706.00	\$ 705.50
5	REAR BUMPER TOWING EYE COVER - LH	1	\$	43.00	\$ 42.60
6	REAR TAIL LIGHT - LH	1	\$	457.00	\$ 457.00
7	REAR BUMPER CARRIER	1	\$	651.00	
8	HEX BOLT	6	\$	30.00	
9	REAR BUMPER PARKING AID SENSOR	2		TBC	
10	REAR BUMPER PARKING AID SENSOR SEAL	4	\$	6.00	
11	REAR BUMPER WHEEL ARCH COVER - LH / RH	2	\$	1,056.00	\$ 1,055.00
12	SUNDRIES		\$	250.00	\$ 1.40
TOTAL SPARE PARTS			:	\$ 5,783.00	\$ 3,141.50
TOTAL LABOUR CHARGES			:	\$ 4,672.00	\$ 3,472.00
GRAND TOTAL			:	\$ 10,455.00	\$ 6,613.50

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-08/12/21

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT