

CHOO MOTOR SPRAY PAINTER
1 KAKI BUKIT AVE 6 #01-39 AUTOBAY
SPORE 417883

VEHICLE No: XE 2480Z

1PC	FRONT BUMPER	DIS	985	\$1,320.00	✓
1PC	FRONT BUMPER SIDE N/S	DIS	655	\$685.00	✓
1PC	FRONT BUMPER INNER BRACKET ASSY	DIS	1100	\$1,845.20	✓
1PC	FRONT BUMPER TOP STEP PROTECTOR N/S	CU7/7W/245		\$250.00	✓
1PC	FRONT BUMPER FOG LAMP N/S	one		\$185.00	✓
1PC	FRONT BUMPER SIDE BLACK GARNISH N/S	DIS		\$118.00	✓
1PC	HEADLAMP N/S	one	1150	\$1,450.00	✓
1PC	FRONT FOOT STEP N/S	one		\$690.00	✓
1PC	FRONT FOOT STEP SIDE GARNISH N/S	one	1120	\$1,150.00	✓
1PC	FRONT FOOT STEP REFLECTOR N/S	scr	40	\$50.00	✓
1PC	FRONT FOOT STEP TOP SIDE GARNISH N/S	one	1250	\$1,280.00	✓
1PC	FRONT DOOR OUTER PILLAR N/S	R		\$1,109.00	X
1PC	FRONT DOOR N/S	R		\$3,220.00	X
1PC	OIL COOLER	Bent/2un	2200	\$2,840.00	✓
1PC	OIL COOLER BRACKET	R		\$645.00	X
1PC	INTER COOLER	3un		\$3,980.00	X
				\$20,817.20	

TO CHECK WIRING	\$50.00	20
TO SPRAY RUST PROOFING	\$100.00	30
TO DISMANTLE & REPLACED OIL COOLER	\$250.00	100
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,800.00	900
TO PUTTY & SPRAY PAINTING	\$1,800.00	900
TOTAL	\$24,817.20	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-9738
10%
P-8764.20
1.1950.00
10714.2
20%
85.71