



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD C/O SEAH ONG & PARTNERS LLP 36 ROBINSON ROAD #12-03 CITY HOUSE SINGAPORE 068877		Ref: CC4/ASM21011052/Upa3q2 Date: 14/07/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMJ 5860U	Veh. Inspected	SJZ 7699H
Policy No.	VPA/P2277912	Coverage (\$)	0.00
Claim No.	22.29758	Excess (\$)	0.00
Assign From		Assign Date	28/10/2021
2. Vehicle Particulars & Condition			
Make & Model	B.M.W. 320I (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	WBADV32070E491801	Colour	WHITE
Odometer	107165 KM	Steering	AFFECTED
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45 R17	CONTINENTAL	6 mm
L/H Front Tyre	225/45 R17	CONTINENTAL	6 mm
R/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm
L/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S & N/S FRONT PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	18/10/2021	Inspection Date	28/10/2021
Survey held at	15 Kaki Bukit Road 4, Bartley Biz Centre, #01-53		
Repairer	ZOOM AUTOWERKS PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days	