



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

Not Authored

29 November 2021

28/10/21

2/s #
14 hrs.

REG NO.: SJZ 7699 H
MAKE/MODEL: BMW 320i

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Front bonnet Bent/Crue 2108.30	2,650.00 ✓
2	Front bonnet hinges R	186.40 X
1	Front bonnet lock SC	255.00 X
1	Front bonnet logo New	71.60 ✓
1	Front bonnet rear rubber New	42.00 ✓
2	Front headlamps n/s n/a o/s Crue 2850.00	6,284.50 IPC
2	Front headlamp lower brackets n/s n/a o/s Crue 115.00	226.00 IPC
1	Front headlamp washer nozzle pen Crue	125.00 ✓
1	Front headlamp washer nozzle hose line Torn 60.00	75.00 ✓
2	Front grilles 11	291.40 X
1	Front bumper Dis	1,357.90 ✓
1	Front bumper centre grille Torn	97.00 ✓
2	Front bumper fog lamps o/s Crue 425.30	942.80 IPC
1	Front bumper inner sponge Torn 148.20	165.00 ✓
2	Front bumper side grilles o/s Torn 62.50	166.30 IPC
2	Front bumper side grille mouldings NS	152.50 X
1	Front bumper lower cover Torn 288.00	399.70 ✓
1	Front bumper reinforcement R	726.00 X
1	Front bumper reinforcement stay o/s DA	150.00 ✓
2	Front bumper side retainers o/s Crue 35.00	72.40 IPC
1	Front bumper top rubber seal New	90.00 ✓
1	Front bumper tow hook cover n.s 32.00	52.60 ✓
1	Front bumper nozzle cover o/s Torn 38.00	68.00 ✓
1	Front support panel Crue	756.25 ✓
1	Front support panel top garnish NS	100.00 X
1	Front support panel side garnish n.s	120.00 X
1	Air con condenser 11	1,185.00 X
2	Front door glass shattered 0725 x 2 = 1450	1,685.00 ✓
1	Front fender - RH Dis 833.00	933.00 ✓
1	Front fender bracket Bent	75.00 ✓
1	Front fender inner panel R	345.00 X
1	Front fender signal lamp Crue	78.00 ✓
1	Front fender wheel housing R	780.00 X
1	Front fender front inner shield Torn	185.00 ✓
1	Front fender rear inner shield Torn	145.00 ✓
1	Front fender inner shield lower extension NS	120.00 X
		<u>\$ 21,154.35</u>

c/f:

\$

21,154.35

1	Front wiper tank	Be	\$	155.00	✓
2	Front alloy wheel rims	100/bent 600x22	\$	2,549.40	1200 s/n
2	Front wheel hub w/bearings	Dyed	\$	900.00	✓
2	Front shock absorbers	Bent	\$	1,170.00	✓
2	Front knuckle arms	Bent	\$	1,140.00	✓
2	Front control arms	Bent	\$	850.00	✓
2	Front lower arms	MS Bent o/s cro	\$	760.00	✓
2	Front stay arms	11	\$	976.00	X
2	Front top arms	11	\$	900.00	X
1	Power steering rack assy	811	\$	2,424.00	X
1	Front tie rod o/s	Bent 265	\$	450.00	✓
2	Front stabilizer bar links	11	\$	160.00	X
1	Drive shaft -RH	11	\$	1,823.00	X
1	Steering wheel air bag	Actual	\$	1,485.00	✓
1	Steering wheel clock spring sensor	Actual	\$	241.50	✓
1	Front windscreen glass	BAD 1233.20	\$	1,400.00	✓
1	Front windscreen moulding	ner	\$	85.00	✓
1	Front dashboard	Torn/Bys 1820.00	\$	2,200.00	✓
1	Front passenger air bag	Actual	\$	1,350.00	✓
2	Front seat belt buckles	@ Actual @ 325 x 2 = 650	\$	840.00	✓
2	Front head rest crash - active repair kits	11	\$	470.00	X
2	Rear head rests	Actual	\$	840.00	✓
1	Rear battery lead positive cable	Actual 250.00	\$	488.90	✓
1	Front Engine Mountings	@ Torn	\$	589.60	✓
			\$	45,401.75	
			Less 5%	\$	2,270.09
			\$	43,131.66	

SPECIAL NETT ITEMS

1	Front bumper clip (1 set)	ner	\$	60.00	50
1	Front number plate	11	\$	50.00	X
1	Front fender inner shield clip (1 set)	ner	\$	65.00	50
2	Front tyres	o/s cut/dyed 4x250 x 1702	\$	1,200.00	175 s/n
1	Front windscreen sealant	ner	\$	80.00	40
1	ERP bracket	ner	\$	35.00	20
			\$	1,490.00	

S/N

LABOUR CHARGES

1	To check wiring and reset headlamps focusing.	\$	80.00	30
2	To remove and refit front undercarriage.	\$	600.00	280
3	To conduct wheel alignment.	\$	180.00	80
4	To remove, replace air-con condenser, refill gas & conduct leakage test.	\$	180.00	100
5	To remove and refit dashboard.	\$	350.00	250
6	To remove and refit front windscreen glass.	\$	180.00	120
7	To apply undercoating.	\$	200.00	60
8	Panel beating. <i>including repair, realign coupe roof</i>	\$	2,000.00	1500
9	To re-spray painting on the affected areas.	\$	1,800.00	1100
10	To diagnose erase fault memory after repair.	\$	400.00	80
		\$	5,970.00	

\$ 50,591.66

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damage
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-2540235
54
P-24132-23
S.N 1535
L-3600