

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

Y/P 8730T
TP/FC

M/S : MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

TEL: 65073848 FAX: 65073849

ATTN: Motor Claim Department \ MR YAP/MR

Estimate No: ES2191181/WS
Date: 09 Dec 2021
Policy No:
Veh Reg No: YP8730T
Make/Model: MITSUBISHI MIT.
CANTER
FEB71ER3SDEN

WS Ref: TP FC
Claim Type: Third Party
Accident Date: 25/10/2021
TP Veh Reg No: SMB282M


Not Withheld
Recovery After Repair
4 days

Chassis No: FEB71EA25053
Engine No: 4P10D10834
Reg. Date: 21/06/2018

Estimate Repair Cost to Vehicle No :YP8730T

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
Labour				
1 TO REPAIR FREEZER BOX LH SIDE PANEL FRAME	550.00	1 LA	550.00	400
2 TO PUTTY & RESPRAY ON LH SIDE PANEL	800.00	1 LA	800.00	550
3 TO REWRITE ADVERTISEMENT ON WHOLE LH PORTION	1,300.00	1 LA (Bill)	1,300.00	800
			2,650.00	2,650.00
			Total	S\$ 2,650.00
			Add GST @ 7%	185.50
			Total Amount Payable	S\$ 2,835.50

For Cheng Hoe Motor Pte Ltd


AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: