

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/TP/0881/2021/JT  
DATE : 28-Oct-21  
V/IP : 51055

VEHICLE **NOT IN** WORKSHOP. KINDLY ARRANGE SURVEY 29/10/21

YOUR INSURED VEH NO : SGV 2307 D

## BUDGET DIRECT INSURANCE

190 CLEMENCEAU AVENUE

#03-01

SINGAPORE SHOPPING CENTRE

SINGAPORE 239924

OWNER'S NAME : MS SHIVKUMAR RADHIKA  
ADDRESS : 112 TANJONG RHU ROAD  
#16-01  
SINGAPORE 436929  
TELEPHONE : HP +65 96984288  
TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : 5121096665  
VEHICLE NO : SMY 2547 R  
MODEL CODE : AUDI Q3 1.4 TFSI S TRONIC  
MODEL YEAR : 25/2/2021  
ENGINE NO : CZD C25686  
CHASSIS NO : WAUZZZF30M1068685  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 24-Oct-21  
PLACE OF ACCIDENT : 112 TANJONG RHU ROAD  
BASEMENT CARPARK

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMY 2547 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ <del>400.00</del> 250	
3	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY RHS FRONT DOOR.	S/N \$ 280.00 ✓	
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. TO REPAIR RHS FRONT DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ <del>2,800.00</del> 1000	
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND RHS FRONT DOOR.	\$ <del>3,000.00</del> 1650	
6	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00 ✓	
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ <u>7,432.00</u></b>	



# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHALI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## **MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 2547 R**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>schnd</i>	1 S	1,008.00 ✓	806.40
2	FRONT BUMPER CLOSING ELEMENET - RH	1 S	59.00 ✗	
3	FRONT BUMPER GRILLE - RH (BLACK)	1 S	110.00 ✗	
4	FRONT BUMPER LOWER CLOSING ELEMENT	1 S	190.00 ✓	
5	FRONT BUMPER SPOILER	1 S	383.00 ✗	
6	FRONT BUMPER AIR GRILLE - RH	1 S	153.00 ✗	
7	FRONT BUMPER GUIDE SECTION - RH <i>N/A</i>	1 S	39.00 ✗	
8	FRONT FENDER - RH <i>Dented</i>	1 S	1,286.00 ✓	1028.80
9	FRONT FENDER ATTACHMENT PARTS <i>N/A</i>	1 S	63.00 ✗	
10	FRONT FENDER BRACE - RH <i>2 N/A</i>	1 S	88.00 ✗	
11	FRONT FENDER BRACKET - RH <i>1 Nec</i>	1 S	32.00 ✗	
12	FRONT WHEEL HOUSING LINER - RH	1	TBC ✗	
13	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>1 N/A</i>	1 S	101.00 ✗	
14	FRONT FENDER COVER <i>N/A</i>	1 S	16.00 ✗	
15	HEADLIGHT MOUNTING - RH <i>N/A</i>	1 S	118.00 ✗	
16	HEADLIGHT - RH <i>cut</i>	1 S	5,589.00 ✓	4471.20
17	HEADLIGHT LIFT CYLINDER - RH <i>3 N/A</i>	1 S	210.00 ✗	
18	HEADLIGHT LIFT CYLINDER HOSE <i>1 N/A</i>	1 S	80.00 ✗	
19	FRONT WHEEL ARCH COVER - LH / RH <i>N/A</i>	2 S	536.00 ✓	428.80
20	FRONT DOOR LOWER COVER - RH <i>N/A</i>	1 S	268.00 ✗	
<b>SUB TOTAL SPARE PARTS</b>		:	<b>\$ 10,329.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2123 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 2547 R

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	FRONT DOOR WINDOWE SLOT SEAL - RH <i>new</i>	1	\$	224.00	
22	TYRE RIM - RH <i>new cut</i>	1	\$	1,262.00	✓ 1009.60
23	SUNDRIES <i>new</i>		\$	300.00	✓ 15.84,
TOTAL SPARE PARTS		:	\$	12,115.00	
TOTAL LABOUR CHARGES		:	\$	7,432.00	
GRAND TOTAL		:	\$	19,547.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.



# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TFL 6366 2323 FAX 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adrian Lim  
29/00/2001

OS  
Not Authorised, 05 Days  
SLS

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU Acknowledged by Repairer  
CLAIMS CONSULTANT

Date:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company