



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:YVONNE		Ref: CC4/ASM21011062/Apa3q2 Date: 12/07/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 6046D	Veh. Inspected	GBK 8255Y
Policy No.	P2419138	Coverage (\$)	0.00
Claim No.	S1M03KWR	Excess (\$)	0.00
Assign From		Assign Date	28/10/2021
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HIACE	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	JTFHT02P900250946	Colour	SILVER
Odometer	39514 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15C	BRIDGESTONE	6 mm
L/H Front Tyre	195 R15C	BRIDGESTONE	6 mm
R/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm
L/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/10/2021	Inspection Date	28/10/2021
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days	